



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 KIA SPORTAGE

EX | 95,915 KM

VIN: KNAPC8121F7717475

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Ventilated Seats

Basic Details

 Kilometers	95915	 Specs	Yes
 Engine	2.4L	 Option Type	Full Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	10 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KNAPC8121F7717475		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Rear Defogger	
Automatic Headlights	
Cruise Control	
Steering Mounted Audio Controls	
Ventilated Seat	
Central Armrest	



Exteriors

Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Halogen Headlights	✓
HID Headlights	✓		



Safety & Security

Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		



Performance

Hill Descent Control	✓	Differential Locks	✓
----------------------	---	--------------------	---



Entertainment

Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off !
< 5mm

Rear left door



Rear right door



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm



Right Fender

Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip-off < 8mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber



Beading Fair Use Wear

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

Windshield Condition

Front Windshield

Condition: Passenger Side/Stone Chip		
Mark<8mm, Driver Side/Stone Chip		Rear Windshield
Mark<5mm		

Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			

Cowl Top

Cowl Top	
----------	--

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	

Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition



Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Scratch < 50mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Front Right Speakers: Voice not Clear/Faulty, Minor Crack/Tear

Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓		

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light Scuffing/ Disfiguration/Melted	!	Central Console	✓
--	---	-----------------	---

Cup Holder

✓	Glove Box	✓
---	-----------	---

Steering Wheel

Color Faded	!	Sunvisor	
		Left: Sunvisor LHS Minor Crack/Fair Use Wear	!

Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓
---	---	----------------------	---

Seat Belts

✓	Head Rest	✓
---	-----------	---

Door Controls And Trim

✓	Grab Handle	✓
---	-------------	---

Carpet

✓	Headliner	
✓	Front Left: Light Smudge/Disfiguration, Light Scuffing	!

Rear View Mirror

✓	Toolkit	✓
---	---------	---

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
---------------------------	---	--------------------------	---

Right Hand Side Front Tyre

✓	Right Hand Side Rear Tyre	✓
---	---------------------------	---

Spare Tyre

✓		

Tyres Depth (Remaining)

LHS Front Tyre	<85%	LHS Rear Tyre	<85%
----------------	------	---------------	------

RHS Front Tyre

<85%	RHS Rear Tyre	<85%
------	---------------	------

Spare Tyre

<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE