



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 LAND ROVER DISCOVERY

SPORT | 84,806 KM

VIN: SALCA2BG7GH544659

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	84806	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	12 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	SALCA2BG7GH544659		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Rear Defogger		Central Armrest	
Automatic Headlights			



Exteriors

Fog Light Front



Running Lights



Rear Bumper Spoiler



HID Headlights



Performance

Paddle Shift



Hill Descent Control



Safety & Security

Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



USB Charging Port



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Dent < 30mm, Scratch < 50mm		Panel: Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Low Visual Dent < 30mm	


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
Bonnet: Acid Marks/ Bird Dropping < 5mm	

Trunk Condition

Trunk	
-------	---





Trunk condition




































Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	

Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Body: Scratch < 50mm		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel Arch		Antenna	
Grill Condition		Monogram	
Window Glass		Wiper	
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System

Condition: Available - SD Card Missing



Music System



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Box: Minor Disfiguration



Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery Driver Seat: Minor Smudge/ Cracks		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner Front Left: Light Smudge/Disfiguration	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE