



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 PEUGEOT 3008

ALLURE | 91,205 KM

VIN: VF3M45GY2KS004885

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort












Power driver seat, Memory Seats

Basic Details

 Kilometers	91205	 Specs	Yes
 Engine	1.6L	 Option Type	Full Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	VF3M45GY2KS004885		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Rear Defogger	
Central Armrest		MagSafe Wireless	

		Charging	
Automatic Headlights			
Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
LED Headlights		Halogen Headlights	
Safety & Security			
Lane Departure Warning System		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
Performance			
Paddle Shift			
Entertainment			
Bluetooth Player		Apple Play	
Android Auto Play		USB Charging Port	
Infotainment System		USB player	





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door	

Fenders Condition

Left Fender		Right Fender Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm	
-------------	---	--	---

Quarter Panels Condition

Left Quarter Panel Condition: Chip<5mm		Right Quarter Panel	
---	--	---------------------	--


Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper 

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm 

Trunk Condition

Trunk 

Trunk condition

Trunk 

Roof Condition

Roof 

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓

Wiper 

Panel Condition

Rear Trunk Panel 

Engine & Transmission

Engine

Engine Body 

Engine Performance 

Engine Oil (Condition & Level) 

Exhaust System 

Turbocharger/ Supercharger 

Radiator Condition 

Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Tank 

Transmission Operation

Gear Shifting 

Gear shift 

Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake 

Brake Master Cylinder 

Brake Disc & Brake Pad 

Brake Fluid 

Pedals 

Suspension

















Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<45%	LHS Rear Tyre	<45%
RHS Front Tyre	<45%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE