



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2020 VOLKSWAGEN PASSAT S | 121,471 KM

VIN: WVWAR7A33LC000492

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Apple play

Enjoy your drive with apple play



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Parking Sensors Front	•	Parking Sensors Rear	✓
Reverse Camera	•	Traction Control	✓
Airbag Curtain Shield	•	Airbag Driver Front	✓
ABS	•	Central Locking	✓
Child Safety Locking	•		
Exteriors			
Running Lights	✓	LED Headlights	✓
Д в Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition Left Running Board Front Left Sill Trim: Minor Scuffing < 80mm	(!)	Right Running Board	•
Windshield Condition Front Windshield Condition: Passenger Side/Stone Chip Mark<8mm	(!)	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition Left Hand Side Mirror Body: Chip < 5mm, Light Scuffing < 50mm	!	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓

Panel Condition			
Rear Trunk Panel	✓		
■ Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		
Steering, Suspension & Brakes			
Steering, Suspension & Brakes Steering			
	✓		
Steering	✓		
Steering Steering wheel		Brake Master Cylinder	✓
Steering Steering wheel Brake System	<!--</td--><td>Brake Master Cylinder Brake Fluid</td><td></td>	Brake Master Cylinder Brake Fluid	
Steering Steering wheel Brake System Parking Brake	<!--</td--><td></td><td>*</td>		*
Steering Steering wheel Brake System Parking Brake Brake Disc & Brake Pad	•		
Steering Steering wheel Brake System Parking Brake Brake Disc & Brake Pad Pedals	•		*
Steering Steering wheel Brake System Parking Brake Brake Disc & Brake Pad Pedals Suspension			
Steering Steering wheel Brake System Parking Brake Brake Disc & Brake Pad Pedals Suspension Shock Absorbers			
Steering Steering wheel Brake System Parking Brake Brake Disc & Brake Pad Pedals Suspension Shock Absorbers Electricals, Controls & Lights			*

Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System Condition: Available - Android Auto & Apple CarPlay	(!)
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	•
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	~
USB Charging Port	✓	Power/ Manual Windows	✓
Interiors & Luggage			
Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	•
Steering Wheel	✓	Sunvisor	✓

Seat Upholstery	✓	Manual Seat Movement	•
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	•
Carpet	✓	Headliner	•
Rear View Mirror	✓	Toolkit	•
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE