



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN MICRA**

**S | 74,107 KM**

VIN: MDHAK3CR6LG001661

## Car highlights



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat



### **Airbag safety**














Airbag Driver Front



### **Tilt Steering wheel**









Tilt steering wheel for extra comfort

## Basic Details

 Kilometers	<b>74107</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>HATCHBACK</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
Seating Capacity	<b>5 Seats</b>	Number of keys	<b>2 Keys</b>
 VIN number	<b>MDHAK3CR6LG001661</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Safety &amp; Security</b>			
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Comfort &amp; Convenience</b>			
Rear Defogger			



## Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door

Moulding: Paint Chip-off < 5mm



Front right door

Frame: Light Scuffing < 50mm



Rear left door

Handle: Paint Chip-off < 5mm



Rear right door

Moulding: Paint Chip-off < 5mm



### Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm



Right Fender



### Quarter Panels Condition

Left Quarter Panel

Trim: Light Scuffing<80mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



### Trunk conditon

Trunk



### Roof Condition

Roof



Pillars Condition

Left A Pillar	⚠	Right A Pillar	✓
Inner Condition: Fair Use Wear			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓

Running Board Condition

Left Running Board	⚠	Right Running Board	✓
Condition: Light Scuffing < 80mm			

Windshield Condition

Front Windshield	✓	Rear Windshield	✓
------------------	---	-----------------	---

Structural Assessment

Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	⚠
Firewall Condition	✓	Condition: Light Scuffing < 80mm	
Head Light Support Condition	✓	Cowl Top	✓

Cowl Top

Cowl Top	✓
----------	---

Rear View Mirror Condition

Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓

Alloy Wheel/ Rim

Spare Alloy/ Rim Condition	✓
----------------------------	---

Wheel Arch

Wheel Arch	✓	Wheel cover	✓
------------	---	-------------	---

Antenna

Antenna	✓	Grill Condition	⚠
		Light Scuffing < 50mm	

Monogram

Monogram	✓	Window Glass	✓
----------	---	--------------	---

Wiper 

Panel Condition

Rear Trunk Panel   
Scratch < 50mm

---

## Engine & Transmission

Engine

Engine Body  Engine Performance 


Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Cap  Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

---

## Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Pedals 

Suspension

Shock Absorbers 

---

## Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	⚠	Heater	✓
Light Scuffing			
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing	⚠
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor Left: Sunvisor LHS Minor Crack/Fair Use Wear	⚠
Seat Upholstery	✓	Manual Seat Movement	✓



Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear		Toolkit	
Rear View Mirror			

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
---------------------------	--	--------------------------	--

Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
----------------------------	--	---------------------------	--

Spare Tyre			
------------	--	--	--

### Tyres Depth (Remaining)

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
----------------	------	---------------	------

RHS Front Tyre	<55%	RHS Rear Tyre	<65%
----------------	------	---------------	------

Spare Tyre	<75%		
------------	------	--	--



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE