



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 TOYOTA COROLLA

HYBRID SE | 91,870 KM

VIN: RKLBA0BE0L1000418

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat










Basic Details

 Kilometers	91870	 Specs	Yes
 Engine	1.8L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Hybrid
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	RKLBA0BE0L1000418		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Central Armrest	
 Safety & Security			
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Entertainment			
Bluetooth Player		USB player	
 Exteriors			
Halogen Headlights			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Scratch < 50mm



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm



Right Fender

Right Fender: Paint Chip-off < 5mm, Dent < 30mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Right Quarter Panel

Condition: Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip < 8mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar

Inner Condition: Fair Use Wear



Right A Pillar

Inner Condition: Light Scuffing



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar

Low Visual Dent < 50mm



Right B to C Pillar Beading



Left C Pillar

Scratch < 50mm



Running Board Condition

Left Running Board

Condition: Scratch < 80mm



Right Running Board

Condition: Light Scuffing < 80mm



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor

Condition: Light Scuffing < 80mm



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover

Front Right: Face/ Scuffs < 50mm



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Paint Chip Off < 5mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger			
Extensive Wear Of Strip	!	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Light Scuffing/Crack	!	Box: Minor Crack/Fair Use Wear/ Scuffing	!

Cup Holder		Glove Box	
Steering Wheel Color Faded		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Left Door: Light Scuffing		Grab Handle	
Carpet Trunk Floor Carpet: Wear & Tear < 80mm		Headliner Front Left: Light Smudge/Disfiguration, Light Scuffing	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE