



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 NISSAN ALTIMA**

**SV | 81,806 KM**

VIN: 1N4BL4A96LC244460

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**


Power driver seat

Basic Details

 Kilometers	81806	 Specs	Yes
 Engine	2.5L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1N4BL4A96LC244460		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Collision Warning System		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



### Comfort & Convenience

Climate Control AC



Cruise Control



Rear Armrest with  
cupholder



Steering Mounted Audio  
Controls



Rear Defogger



Central Armrest



Remote Engine Start



Automatic Headlights



### Exteriors

Fog Light Front



Halogen Headlights



### Entertainment

Bluetooth Player



Apple Play



Android Auto Play



USB Charging Port



Infotainment System



USB player







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Panel: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm		Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm			

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Low Visual Dent < 30mm, Light Scuffing<50mm	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror		Right Hand Side Mirror	✓
Body: Light Scuffing < 50mm	!		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Rim: Alloy Edge Scuffing > 50mm		Rim: Alloy Edge Scuffing > 50mm	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing < 80mm	!	Rim: Alloy Face/Light Scuffing<50mm, Alloy Edge/Scuffing<80mm	!

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Grill Condition	⚠
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

## 🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## 🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch





Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel Steering Wheel Fair Use Wear	!	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<85%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE