



### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2020 MITSUBISHI PAJERO GLS LOWLINE | 43,459 KM

## Car highlights



### **Low Mileage**

This car has been driven less than 15,000 km a year



### Four wheel drive

This car has a Four wheel drive



## **Amazing Comfort**


Power driver seat



## **Tilt Steering wheel**


Tilt steering wheel for extra comfort


### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.





## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	~	Right Running Board Right Foot Board: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	•	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>✓</b>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel Arch	<b>✓</b>	Antenna	<b>✓</b>
Grill Condition Light Scuffing < 50mm	(!)	Monogram	<b>✓</b>
Window Glass	•	Wiper	<b>✓</b>

Panel Condition			
Rear Trunk Panel	<b>✓</b>		
<b>ℰ Engine &amp; Transmission</b>			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Battery			
Battery Terminal & Tightness	<b>✓</b>		
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
4*4 Condition (If Applicable)	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Pedals	<b>✓</b>		
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>	Spare Key(s)	<b>✓</b>
Door Locks			

Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Cruise Control	•
Infotainment Display	<b>✓</b>	Engine Sensors	•
OBD Connector	<b>✓</b>	Music System	<b>✓</b>
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Turn Signal Lights Right ORVM: Light Scuffing < 50mm	(!)
Daylight Running Lights	<b>✓</b>	License Plate Light	<b>✓</b>
Fog Lights	<b>✓</b>		
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Blower Switch	<b>✓</b>	Rear Left AC Vent	<b>✓</b>
Parking Sensors	<b>✓</b>	Rear Defogger	<b>✓</b>
USB Charging Port	<b>✓</b>	Power/ Manual Windows	<b>✓</b>
Interiors & Luggage			
Dashboard And Instrument Panel	•	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	<b>✓</b>	Glove Box	•
Steering Wheel	•	Sunvisor	<b>✓</b>

Seat Upholstery	<b>✓</b>	Manual Seat Movement	•
Seat Belts	~	Head Rest	<b>~</b>
Door Controls And Trim	~	Grab Handle	•
Carpet	•	Headliner Rear Left: Smudge/Disfiguration	(!)
Rear View Mirror	•	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	<b>✓</b>		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<85%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE