



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 FORD EXPLORER

XLT 4WD | 117,483 KM

VIN: 1FM5K8D81JGC01666

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat




Basic Details

 Kilometers	117483	 Specs	Yes
 Engine	3.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1FM5K8D81JGC01666		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
Halogen Headlights		HID Headlights	
 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	

Rear Defogger	✓	Central Armrest	✓
Automatic Headlights	✓		
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Performance			
Hill Descent Control	✓		
 Entertainment			
Bluetooth Player	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

Exterior



Doors condition

Front left door		Front right door	
Handle: Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Scratch < 50mm, Paint Chip-off < 5mm		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm		Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent < 30mm, Paint Chip-off < 5mm		Condition: Scratch < 50mm, Paint Chip-off < 5mm	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
Door Trim: Scuff/ Disfiguration< 50mm	

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	!	Left B to C Pillar Beading	✓
Light Scuffing			
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	!	Right Running Board	!
Condition: Fair Use Wear		Front Right Sill Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield	✓	Rear Windshield	!
		Tint Fair Use Wear < 30mm	
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights

Left Fog Light: Scuff Marks > 50mm



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port

Rear: Cigarette Lighter Missing



Power/ Manual Windows





Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Trim: Light Scuffing/Disfiguration



Central Console

Gear Shift Knob: Knob Fair Use Wear



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE