



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2020 MAZDA CX 5 GS | 107,200 KM

VIN: JM7KFAWL0L0353606

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Traction Control	✓	Airbag Curtain Shield	✓
Airbag Driver Front	•	ABS	✓
Central Locking	•	Child Safety Locking	✓
ℚ a Entertainment			
Littertaniment			
	•	USB player	✓
Bluetooth Player Exteriors	•	USB player	•


150 Point Detailed Inspection Report

Roof Condition

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	(!)
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition Left Running Board Front Left Sill Trim: Scratch < 80mm	(!)	Right Running Board	•
Windshield Condition Front Windshield	✓	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition Left Hand Side Mirror Body: Paint Chip-off < 5mm	<u>!</u>	Left Side Mirror	•
Right Side Mirror Body: Paint Chip-off < 5mm	!	Right Hand Side Mirror	•
Alloy Wheel/ Rim Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	(!)	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff > 80mm	(!)
Spare Alloy/ Rim Condition	✓		





Electricals, Controls & Lights

Keys

Master Key

Door Locks

Child Safety Locking

Dashboard

Instrument Panel

Airbags

Airbags

Controls Cruise Control

Infotainment Display

Engine Sensors

OBD Connector

Music System

Camera

Lights

Air Conditioning

Headlight Interior Lights

Tail Light Cluster

Turn Signal Lights

Daylight Running Lights

License Plate Light

AC Cooling AC Switch

AC System Leaks Center AC Vent

Front Right AC Vent

Heater

Rear Defogger

USB Charging Port

Power/ Manual Windows

Dashboard And Instrument Panel	•	Central Console Cigarette Lighter: Cigarette Lighter Missing	(!)
Cup Holder	✓	Glove Box	•
Steering Wheel Steering Wheel Fair Use Wear	(!)	Sunvisor	•
Seat Upholstery	•	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Rear Left Door: Light Scuffing	(!)	Grab Handle	•
Carpet Trunk Floor Carpet: Wear & Tear < 80mm	(!)	Headliner	•
Rear View Mirror	✓	Toolkit	✓
Rear View Mirror Tyres	~	Toolkit	•
	•	Toolkit	
Tyres		Toolkit Left Hand Side Rear Tyre	
Tyres Condition			
Tyres Condition Left Hand Side Front Tyre	<!--</td--><td>Left Hand Side Rear Tyre</td><td></td>	Left Hand Side Rear Tyre	
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre	<!--</td--><td>Left Hand Side Rear Tyre</td><td></td>	Left Hand Side Rear Tyre	
Tyres Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	75%	Left Hand Side Rear Tyre	<75%
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre Tyres Depth (Remaining)	75% 75%	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE