



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 INFINITI Q50**

**TURBO | 112,816 KM**

VIN: JN1CV7AP3GM841058

## **Car highlights**



### **Supercharger/turbocharger**

This car has a Supercharger/turbocharger



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat, Memory Seats

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 112816            |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Basic Option         |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive     |
|  Body Type        | SEDAN             |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | JN1CV7AP3GM841058 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                             |   |
|--|---|-----------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Climate Control AC   |  | Cruise Control              |  |
| Memory Seats   |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls  |  | Power Folding Mirrors       |  |
| Rear Defogger  |  | Central Armrest             |  |
| Automatic Headlights   |  |                             |   |



## Exteriors

Fog Light Front



Running Lights



LED Headlights



## Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



USB player







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior


### Doors condition

|  |   |                  |   |
|--|---|------------------|---|
| Front left door                                    |  | Front right door |  |
| Rear left door                                     |   |                  |   |
| Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm |  | Rear right door  |  |

### Fenders Condition

|                                   |   |                                   |   |
|-----------------------------------|---|-----------------------------------|---|
| Left Fender                       |   | Right Fender                      |   |
| Condition: Light Scuffing < 50 mm |  | Condition: Low Visual Dent < 30mm |  |

### Quarter Panels Condition

|                                 |  |                     |  |
|---------------------------------|--|---------------------|--|
| Left Quarter Panel              |  | Right Quarter Panel |  |
| Condition: Low Visual Dent<30mm |  |                     |  |

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|             |   |
|-------------|---|
| Rear Bumper |  |
|-------------|---|

### Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|               |   |                |   |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

|  |   |                             |   |
|--|---|-----------------------------|---|
| Left A to B Pillar Beading                           | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar                                  | ✓ | Left B Pillar               | ✓ |
| Left B Pillar Trim                                   | ✓ | Left B to C Pillar Beading  | ✓ |
| Right C Pillar Trim                                  | ✓ | Right B to C Pillar         | ✓ |
| Right B to C Pillar Beading                          | ✓ | Left C Pillar               | ✓ |
| Running Board Condition                              |   |                             |   |
| Left Running Board                                   | ✓ | Right Running Board         | ✓ |
| Windshield Condition                                 |   |                             |   |
| Front Windshield                                     | ✓ | Rear Windshield             | ✓ |
| Structural Assessment                                |   |                             |   |
| Chassis Condition                                    | ✓ | Radiator Support            | ✓ |
| Apron  | ✓ | Boot Floor                  | ✓ |
| Firewall Condition                                   | ✓ | Cowl Top                    | ✓ |
| Head Light Support Condition                         | ✓ |                             |   |
| Cowl Top   |   |                             |   |
| Cowl Top   | ✓ |                             |   |
| Rear View Mirror Condition                           |   |                             |   |
| Left Hand Side Mirror<br>Body: Light Scuffing < 50mm | ! | Left Side Mirror            | ✓ |
| Right Side Mirror                                    | ✓ | Right Hand Side Mirror      | ✓ |
| Alloy Wheel/ Rim                                     |   |                             |   |
| Left Front Alloy/ Rim                                | ✓ | Left Rear Alloy/ Rim        | ✓ |
| Right Front Alloy/ Rim                               | ✓ | Right Rear Alloy/ Rim       | ✓ |
| Wheel cover  | ✓ | Grill Condition             | ✓ |
| Monogram   | ✓ | Window Glass                | ✓ |
| Wiper  | ✓ |                             |   |
| Panel Condition                                      |   |                             |   |
| Rear Trunk Panel                                     | ✓ |                             |   |



## Engine & Transmission

### Engine

#### Engine Body

Mount Condition: Minor Crack/Fair Use Wear



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Door Locks

Child Safety Locking



|                         |   |                     |   |
|-------------------------|---|---------------------|---|
| Dashboard               |   |                     |   |
| Instrument Panel        | ✓ |                     |   |
| Airbags                 |   |                     |   |
| Airbags                 | ✓ |                     |   |
| Controls                | ✓ | Cruise Control      | ✓ |
| Infotainment Display    | ✓ | Engine Sensors      | ✓ |
| OBD Connector           | ✓ | Music System        | ✓ |
| Camera                  | ✓ |                     |   |
| Lights                  |   |                     |   |
| Headlight               | ✓ | Interior Lights     | ✓ |
| Tail Light Cluster      | ✓ | Turn Signal Lights  | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Fog Lights              | ✓ |                     |   |
| Air Conditioning        |   |                     |   |
| AC Cooling              | ✓ | AC Switch           | ✓ |
| AC System Leaks         | ✓ | Center AC Vent      | ✓ |
| Front Right AC Vent     | ✓ | Heater              | ✓ |
| Rear Blower Switch      | ✓ |                     |   |
| Rear Defogger           | ✓ | USB Charging Port   | ✓ |
| Power/ Manual Windows   | ✓ | Seat Heaters        | ✓ |
| Memory Seats            | ✓ |                     |   |



## Interiors & Luggage

|  |   |                 |   |
|--|---|-----------------|---|
| Dashboard And Instrument Panel                             |   |                 |   |
| Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear | ! | Central Console | ✓ |
| Cup Holder   | ✓ | Glove Box       | ✓ |

|                        |   |                      |   |
|------------------------|---|----------------------|---|
| Steering Wheel         | ✓ | Sunvisor             | ✓ |
| Seat Upholstery        | ✓ | Manual Seat Movement | ✓ |
| Seat Belts             | ✓ | Head Rest            | ✓ |
| Door Controls And Trim | ✓ | Grab Handle          | ✓ |
| Carpet                 | ✓ | Headliner            | ✓ |
| Rear View Mirror       | ✓ | Toolkit              | ✓ |

## Tyres

Tyres Condition

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |

Tyres Depth (Remaining)

|                |      |               |      |
|----------------|------|---------------|------|
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |

Spare Tyre

No spare  
tyre



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE