



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2015 RENAULT DUSTER**

**SE | 174,941 KM**

VIN: VF1HSRCA5FA512134

## Car highlights



### **Bluetooth**

Enjoy your drive with bluetooth



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**
















Power driver seat



### **Airbag safety**








Airbag Driver Front








## Basic Details

 Kilometers	<b>174941</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>4 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>VF1HSRCA5FA512134</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Halogen Headlights			
 <b>Comfort &amp; Convenience</b>			
Steering Mounted Audio Controls			
 <b>Entertainment</b>			

Bluetooth Player		USB player	
 <b>Safety &amp; Security</b>			
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed



## Exterior

### Doors condition


#### Front left door

Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm 

#### Front right door

Frame: Low Visual Dent < 30mm, Light Scuffing < 50mm 

#### Rear left door


Inner Frame: Light Scuffing < 80mm 

#### Rear right door

Handle: Paint Chip-off < 5mm 

### Fenders Condition

#### Left Fender


Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm, Paint Chip-off < 5mm 

#### Right Fender

Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm 

### Quarter Panels Condition

#### Left Quarter Panel

Condition: Low Visual Dent<30mm, Light Scuffing<50mm, Chip<5mm 

#### Right Quarter Panel

Condition: Light Scuffing<50mm, Low Visual Dent < 30mm, Chip<5mm 


### Front Bumper Condition

#### Front Bumper




### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 

### Hood Condition

#### Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 

### Trunk Condition

#### Trunk

Door Trim: Light Scuffing < 50mm 


### Trunk conditon

#### Trunk



### Roof Condition

## Roof

Roof Moulding Condition: Minor Rubber Beading Fair Use Wear 

## Pillars Condition

Left A Pillar  Right A Pillar 

Left A to B Pillar Beading  Right A to B Pillar Beading   
Beading Crack/ Tear < 5mm

Right A to B Pillar  Left B Pillar 

Left B Pillar Trim  Left B to C Pillar Beading 


Right C Pillar Trim  Right B to C Pillar   
Light Scuffing < 80mm


Right B to C Pillar Beading  Left C Pillar   
Light Scuffing < 50mm

## Running Board Condition

Left Running Board  Right Running Board   
Condition: Light Scuffing < 80mm Front Right Sill Trim: Light Scuffing < 80mm

## Windshield Condition

Front Windshield   
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm

Rear Windshield 

## Structural Assessment

Chassis Condition  Radiator Support 

Apron  Boot Floor 

Firewall Condition  Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

## Rear View Mirror Condition

Left Hand Side Mirror  Left Side Mirror   
Body: Chip < 5mm

Right Side Mirror  Right Hand Side Mirror   
Body: Paint Chip-off < 5mm

Alloy Wheel/ Rim

Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	✓
Rim: Alloy Face Light Scuffing < 50mm			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	⚠
Monogram	✓	Light Scuffing < 50mm	
Wiper	✓	Window Glass	✓
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	⚠		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering	
Steering wheel	✓
Brake System	

Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



## Electricals, Controls & Lights

### Keys

Master Key	✓	Spare Key(s)	✓
------------	---	--------------	---

### Door Locks

Child Safety Locking	✓		
----------------------	---	--	--

### Dashboard

Instrument Panel	✓		
------------------	---	--	--

### Airbags

Airbags	✓		
---------	---	--	--

Controls	✓	Infotainment Display	✓
----------	---	----------------------	---

Engine Sensors	✓	OBD Connector	✓
----------------	---	---------------	---

Music System	✓		
--------------	---	--	--

### Lights

Headlight	✓	Interior Lights	✓
-----------	---	-----------------	---

Tail Light Cluster	✓	License Plate Light	✓
--------------------	---	---------------------	---

Fog Lights	✓		
------------	---	--	--

### Air Conditioning

AC Cooling	✓	AC Switch	✓
------------	---	-----------	---

















AC System Leaks	✓	Center AC Vent	✓
-----------------	---	----------------	---

Front Right AC Vent	✓	Heater	✓
---------------------	---	--------	---

USB Charging Port	✓	Power/ Manual Windows	✓
-------------------	---	-----------------------	---



## Interiors & Luggage

Dashboard And Instrument Panel		Central Console Cigarette Lighter: Cigarette Lighter Missing	
Cup Holder		Glove Box	
Steering Wheel Color Faded		Sunvisor	
Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing		Grab Handle	
Carpet		Headliner Rear Left: Smudge/Disfiguration	
Rear View Mirror		Toolkit	

## Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<40%	LHS Rear Tyre	<65%
RHS Front Tyre	<40%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE