



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 TOYOTA COROLLA

XLI | 138,058 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat



Basic Details

 Kilometers	138058	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	RKLBL9HE5K5269110		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	

Central Locking	✓	Child Safety Locking	✓
 Exteriors			
Running Lights	✓	Halogen Headlights	✓
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
USB player	✓		

150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Handle: Scratch < 50mm, Paint Chip-off < 5mm 

Front right door

Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door

Handle: Paint Chip-off < 5mm 

Rear right door

Handle: Paint Chip-off < 5mm 

Fenders Condition

Left Fender


Condition: Dent < 30mm, Scratch < 50mm 

Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm 

Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm 

Right Quarter Panel


Condition: Dent < 30mm, Scratch < 50mm 

Front Bumper Condition

Front Bumper 


Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof 

Pillars Condition

Left A Pillar 

Right A Pillar 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar 


Left B Pillar 

Left B Pillar Trim 

Left B to C Pillar Beading 

Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar 


Running Board Condition

Left Running Board 

Right Running Board 

Windshield Condition

Front Windshield

Condition: Passenger Side/Stone Chip
Mark<8mm 


Rear Windshield 

Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor
Condition: Light Scuffing < 80mm 

Firewall Condition 


Cowl Top 

Head Light Support Condition 


Cowl Top

Cowl Top 

Rear View Mirror Condition


Left Hand Side Mirror
Body: Paint Chip-off < 5mm 


Left Side Mirror 

Right Side Mirror
Body: Paint Chip-off < 5mm 


Right Hand Side Mirror 

Alloy Wheel/ Rim

Left Front Alloy/ Rim
Rim: Alloy Edge/ Scuff < 80mm 

Left Rear Alloy/ Rim
Rim: Alloy Edge/ Scuff < 80mm 

Right Front Alloy/ Rim 

Right Rear Alloy/ Rim
Rim: Alloy Edge/ Scuff < 80mm 


Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Paint Chip Off < 5mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	!	Interior Lights	✓
Left: Light Scuff Marks < 50mm			
Tail Light Cluster	!	Turn Signal Lights	!
Left Tail Lamp: Light Scuffing < 50mm		Right ORVM: Light Scuffing < 50mm	
Daylight Running Lights	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	!	Heater	✓
Light Scuffing			
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Color Faded, Light Disfiguration



Central Console

Gear Shift Knob: Knob Fair Use Wear, Buttons Faded



Cup Holder



Glove Box



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Trunk Floor Carpet: Wear & Tear < 80mm



Headliner

Rear Left: Smudge/Disfiguration, Light Scuffing



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE