



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 TOYOTA COROLLA**

**SE | 117,512 KM**

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**





Power driver seat










Basic Details

 Kilometers	117512	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	RKLBL9HE8K5266363		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Entertainment</b>			
Bluetooth Player		USB player	
 <b>Exteriors</b>			
Halogen Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Inner Frame: Scratch < 50mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Panel: Dent < 30mm, Scratch < 50mm		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Dent < 30mm, Scratch < 50mm		Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Dent < 30mm, Scratch < 50mm	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Paint Faded	

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	


### Trunk conditon

Trunk	
-------	---

### Roof Condition


Roof 


#### Pillars Condition


Left A Pillar  
Inner Condition: Fair Use Wear 

Right A Pillar  
Inner Condition: Light Scuffing 

Left A to B Pillar Beading 

Right A to B Pillar Beading 

Right A to B Pillar  
Light Scuffing < 50mm 

Left B Pillar  
Condition: Scratch < 50mm 

Left B Pillar Trim 

Left B to C Pillar Beading 


Right C Pillar Trim 

Right B to C Pillar 

Right B to C Pillar Beading 

Left C Pillar  
Scratch < 50mm 

#### Running Board Condition

Left Running Board  
Front Left Sill Trim: Scratch < 80mm 

Right Running Board  
Condition: Light Scuffing < 80mm 

#### Windshield Condition

Front Windshield  
Condition: Driver Side/Stone Chip  
Mark<5mm, Passenger Side/Stone Chip  
Mark<8mm 

Rear Windshield 

#### Structural Assessment

Chassis Condition 

Radiator Support 

Apron 

Boot Floor 

Firewall Condition 

Cowl Top 

Head Light Support Condition 

Cowl Top

Cowl Top 

#### Rear View Mirror Condition


Left Hand Side Mirror 

Left Side Mirror 

Right Side Mirror 

Right Hand Side Mirror 

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim  
Rim: Alloy Edge/ Scuff < 80mm 

Left Rear Alloy/ Rim  
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/  
Scuff < 80mm 

Right Front Alloy/ Rim  
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/  
Scuff < 80mm



Spare Alloy/ Rim Condition



Wheel Arch



Antenna



Monogram



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



Right Rear Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/  
Scuff < 80mm



Wheel cover



Grill Condition

Light Scuffing < 50mm



Window Glass



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓





## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light Scuffing/ Disfiguration/Melted



### Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing, Minor Color Low Brightness



Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Light Scuffing



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<85%

LHS Rear Tyre

<45%

RHS Front Tyre

<85%

RHS Rear Tyre

<45%

Spare Tyre

<55%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE