



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2019 NISSAN SUNNY

S | 169,756 KM

VIN: MDHBN7AD7KG664083

Car highlights



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front

Basic Details

 Kilometers	169756	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MDHBN7AD7KG664083		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Comfort & Convenience			
Rear Defogger			



Entertainment

Bluetooth Player



USB player



Exteriors

Halogen Headlights



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Frame Extension Cover: Chip < 5mm

Front right door



Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door



Panel: Scratch < 50mm

Rear right door



Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Condition: Light Scuffing < 50 mm

Right Fender



Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm

Quarter Panels Condition

Left Quarter Panel

Right Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Low Visibility Dent < 30mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Inner Condition: Fair Use Wear

Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Light Scuffing

Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Front Left Sill Trim: Scratch < 80mm

Right Running Board



Front Right Sill Trim: Light Scuffing < 80mm,

Low Visual Dent < 50mm

Windshield Condition

Front Windshield



Condition: Driver Side/Stone Chip

Rear Windshield



Mark<5mm, Passenger Side/Stone Chip

Mark<8mm

Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Condition: Refurbished to RTA standards,
Poor Refurb Job

Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top



Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Antenna



Grill Condition



Light Scuffing < 50mm

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Scratch < 50mm

Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel		Central Console Cigarette Lighter: Cigarette Lighter Missing	
Cup Holder		Glove Box Glove Box: Minor Scuffing/Crack/Fair Use Wear	
Steering Wheel Steering Wheel Fair Use Wear		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE