



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN SUNNY

SV | 106,392 KM

## Car highlights



### Bluetooth

Enjoy your drive with bluetooth



### Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



### Amazing Comfort

Power driver seat



### Airbag safety

Airbag Driver Front

## Basic Details

 Kilometers	<b>106392</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MDHBN7AD8KG680759</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Comfort & Convenience			
Steering Mounted Audio Controls		Rear Defogger	



## Entertainment

Bluetooth Player



USB player



## Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Paint



Chip-off < 5mm

Rear left door



Rear right door

Panel: Paint Chip-off < 5mm

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Dent < 30mm, Scratch < 50mm,



Right Fender



Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Door Trim: Scuff/ Disfiguration < 50mm

Trunk condition

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar Condition: Dent < 30mm, Chip < 5mm
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar Chip < 8mm
Right B to C Pillar Beading		Left C Pillar Chip < 5mm
Running Board Condition		
Left Running Board		Right Running Board
Front Left Sill Trim: Scratch < 80mm		Front Right Sill Trim: Light Scuffing < 80mm
Windshield Condition		
Front Windshield		Rear Windshield
Condition: Driver Side/Scuffing		
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor Condition: Light Scuffing < 80mm
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Spare Alloy/ Rim Condition		
Wheel Arch		Wheel cover

Antenna		Grill Condition Light Scuffing < 50mm	
Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

Controls  Infotainment Display 

Engine Sensors  OBD Connector 

Music System 

### Lights

Headlight  Interior Lights 

Left: Light Scuff Marks < 50mm

Tail Light Cluster  License Plate Light 

### Air Conditioning

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

USB Charging Port  Power/ Manual Windows 

## Interiors & Luggage

Dashboard And Instrument Panel  Central Console 

Dashboard Upholstery: Minor Scuffing/ Disfigurement/ Melted  Box: Minor Crack/Fair Use Wear/ Scuffing 

Cup Holder  Glove Box 

Steering Wheel  Sunvisor 

Steering Wheel Fair Use Wear

Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim			
Front Left Door: Fair Use Wear, Light Scuffing/ Disfiguration		Grab Handle	
Carpet			
Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE