



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 CHEVROLET CRUZE

LT | 128,571 KM

VIN: KL1PM5D57GK304258

Car highlights



Sunroof

This car has a sunroof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat



Basic Details

 Kilometers	128571	 Specs	Yes
 Engine	1.8L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KL1PM5D57GK304258		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Automatic Headlights			
 Exteriors			

Fog Light Front	✓	Running Lights	✓
LED Headlights	✓	Halogen Headlights	✓
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Entertainment			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm		Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Scratch < 50mm, Dent < 30mm		Right Fender: Scratch < 50mm, Dent < 30mm, Paint Chip-off < 5mm	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm		Condition: Scratch < 50mm, Dent < 30mm	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading Beading Crack/ Tear < 5mm	!
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading Beading Crack/ Tear < 5mm	!	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board Condition: Light Scuffing < 80mm, Low Visual Dent < 50mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	!	Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!


Right Front Alloy/ Rim	⚠	Right Rear Alloy/ Rim	⚠
Rim: Alloy Face/ Scuff < 50mm		Rim: Alloy Edge/ Scuff < 80mm	
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	⚠	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	⚠		
Scratch < 50mm			

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  Electricals, Controls & Lights </div>			
Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Radar (If Equipped)	✓
Music System			
Audio Inputs: Connectivity Issue	!		
Sunroof Operation			
Sunroof	✓		
Camera			
Reverse Camera: Lens Damaged/ Blurred	!		
Lights			
Headlight		Interior Lights	✓
Left: Light Scuff Marks < 50mm	!		
Tail Light Cluster		Turn Signal Lights	
Right Tail Lamp: Crack / Fair Use Wear < 5mm	!	Right ORVM: Crack	!
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		

Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	!
		Heater Not Working	
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	
Steering Wheel Fair Use Wear		Left: Sunvisor RHS Vanity Mirror Cover Damage	!
Seat Upholstery			
Passenger Seat: Minor Leather/Fabric Fair Use Wear/Tears, Minor Smudge/Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Rear Left Door: Light Scuffing			
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<75%

RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE