



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2021 MAZDA CX 5 GS | 58,114 KM

VIN: JM7KFAWLXM0610854

# **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### Apple play


Enjoy your drive with apple play



### **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Fog Light Front	•	Rear Bumper Spoiler	•
HID Headlights	<b>✓</b>		
冷 Safety & Security			
Parking Sensors Rear	~	Reverse Camera	<b>✓</b>
Traction Control	~	Airbag Curtain Shield	~
Airbag Driver Front	~	ABS	~
Central Locking	~	Child Safety Locking	<b>~</b>
<b>⊈</b> Entertainment			
Bluetooth Player	~	Apple Play	<b>✓</b>
Android Auto Play	<b>✓</b>	USB Charging Port	•
Infotainment System	<b>✓</b>	USB player	<b>✓</b>

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	<b>✓</b>	Right A Pillar	<b>✓</b>
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	~
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>~</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>~</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>~</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition  Front Windshield  Condition: Driver Side/Stone Chip Mark<5mm	•	Rear Windshield	•
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>~</b>
Right Side Mirror	<b>✓</b>	Right Hand Side Mirror	<b>~</b>
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim	<b>✓</b>
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>~</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel Arch	<b>✓</b>	Wheel cover	<b>✓</b>
Antenna	<b>✓</b>	Grill Condition	<b>✓</b>



Keys			
Master Key	<b>~</b>		
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>~</b>		
Controls	<b>✓</b>	Cruise Control	•
Infotainment Display	<b>✓</b>	Engine Sensors	<b>✓</b>
		Navigation System	
OBD Connector	<b>✓</b>	Condition: Available - SD Card Missing,	(!)
		Available - Android Auto & Apple CarPlay	
Music System	<b>✓</b>	Camera	<b>✓</b>
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster	<b>✓</b>	Turn Signal Lights	<b>✓</b>
License Plate Light	<b>✓</b>	Fog Lights	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Blower Switch	~		
Parking Sensors	<b>✓</b>	Rear Defogger	<b>✓</b>
USB Charging Port	<b>✓</b>	Power/ Manual Windows	<b>✓</b>
🖺 Interiors & Luggage			

Central Console

Dashboard And Instrument Panel

(!)

### Cigarette Lighter: Cigarette Lighter Missing

Cup Holder	<b>✓</b>	Glove Box	<b>✓</b>
Steering Wheel	<b>✓</b>	Sunvisor	<b>✓</b>
Seat Upholstery	<b>✓</b>	Manual Seat Movement	<b>✓</b>
Seat Belts	<b>✓</b>	Head Rest	<b>~</b>
Door Controls And Trim	<b>✓</b>	Grab Handle	<b>~</b>
Carpet	<b>✓</b>	Headliner	<b>~</b>
Rear View Mirror	<b>✓</b>	Toolkit	•
Tyres			
Tyres Condition			
	•	Left Hand Side Rear Tyre	<b>✓</b>
Tyres Condition	<b>⋄</b>	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	✓
Tyres Condition  Left Hand Side Front Tyre	<ul><li></li><li></li><li></li></ul>		✓
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre	<ul><li></li><li></li><li></li></ul>		✓
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre	<75%		<75%
Tyres Condition  Left Hand Side Front Tyre  Right Hand Side Front Tyre  Spare Tyre  Tyres Depth (Remaining)	<75% <75%	Right Hand Side Rear Tyre	<75% <75%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE