



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MITSUBISHI LANCER

GLS HIGHLINE | 81,322 KM

VIN: JMYSRCY1AGU750646

Car highlights



Sunroof

This car has a sunroof



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Music System
















Enjoy your drive with music system



Amazing Comfort




Power driver seat


Basic Details

| | | | |
|--|-------------------|---|-----------------------|
|  Kilometers | 81322 |  Specs | Yes |
|  Engine | 1.6L |  Option Type | Fully Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | JMYSRCY1AGU750646 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | | |
|  Exteriors | | | |
| Fog Light Front |  | Rear Bumper Spoiler |  |

| | | | |
|--|---|----------------------|---|
| Halogen Headlights | ✓ | | |
|  Safety & Security | | | |
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |

150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Handle: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Front right door

Handle: Light Scuffing < 50mm 

Rear left door


Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear right door



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light Scuffing < 50 mm 

Right Fender


Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm 

Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm, Chip<5mm 

Right Quarter Panel

Condition: Light Scuffing<50mm, Low Visual Dent < 30mm, Chip<5mm 


Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm 

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar

Light Scuffing < 50mm



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar

Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar

Light Scuffing < 50mm



Running Board Condition

Left Running Board

Condition: Light Scuffing < 80mm



Right Running Board

Condition: Light Scuffing < 80mm



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Light Scuffing < 50mm



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

| | | | |
|---------------------------------|---|-----------------------|---|
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ! | Right Rear Alloy/ Rim | ✓ |
| Rim: Alloy Edge Scuffing < 80mm | | | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition | ! |
| | | Light Scuffing < 50mm | |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | | | |
| Scratch < 50mm | ! | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|----------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |

| | | | |
|------------------------|---|-------------|---|
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|----------------------------------|---|----------------------|---|
| Keys | | | |
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Engine Sensors | ✓ | OBD Connector | ✓ |
| Music System | | | |
| Audio Inputs: Connectivity Issue | ! | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | | | |
| Left: Light Scuff Marks < 50mm | ! | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Turn Signal Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |

| | | | |
|---------------------|---|-----------------------|---|
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Defogger | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--------------------------------|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner Rear Left: Smudge/Disfiguration | ! |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE