



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 TOYOTA COROLLA**

**XLI | 81,533 KM**

VIN: RKLBB9HE3K5237498

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat










## Basic Details

 Kilometers	<b>81533</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>RKLBB9HE3K5237498</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Entertainment</b>			
Bluetooth Player		USB player	
 <b>Exteriors</b>			
Halogen Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Scratch < 50mm, Paint Chip-off < 5mm



Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel

Condition: Paint Chip-off < 5mm



Right Quarter Panel

Condition: Chip<5mm, Light Scuffing<50mm



### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
		Light Scuffing < 80mm	
		Left C Pillar	!
		Dent < 30mm	
Running Board Condition			
Left Running Board	!	Right Running Board	!
Front Left Sill Trim: Scratch < 80mm		Rear Right Floor Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip	!	Rear Windshield	✓
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	!
		Condition: Light Scuffing < 80mm	
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	!
		Front Right: Face/ Scuffs < 50mm	
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram		Window Glass	
Wiper			
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Drive Axle	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	
Pedals			
Suspension			
Shock Absorbers			













## Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage






Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	ⓘ
Cup Holder	✓	Glove Box Glove Box: Minor Scuffing/Crack/Fair Use Wear	ⓘ



Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear			
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
		Front Left: Light Smudge/Disfiguration	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<85%
Spare Tyre	<85%		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE