



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2015 KIA RIO**

**LX | 85,530 KM**

VIN: KNADN5123F6488332

## **Car highlights**



### **Amazing Comfort**

Power driver seat



### **Airbag safety**

Airbag Driver Front



### **Tilt Steering wheel**
















Tilt steering wheel for extra comfort



### **USB Charging Port**









USB charging port for extra comfort

Basic Details

 Kilometers	85530	 Specs	Yes
 Engine	1.5L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KNADN5123F6488332		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>	
Rear Bumper Spoiler <div></div>	Halogen Headlights <div></div>
<div> Comfort &amp; Convenience</div>	
Rear Defogger <div></div>	
<div> Safety &amp; Security</div>	
Airbag Driver Front <div></div>	ABS <div></div>

Central Locking



Child Safety Locking



Entertainment

USB player







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Inner Beading: Rubber Crack/ Tear < 5mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Handle: Discoloured		Handle: Discoloured	

### Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm		Condition: Paint Chip-off < 5mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Chip<5mm, Low Visual Dent<30mm		Condition: Paint Faded	


### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

### Hood Condition

Hood	
Bonnet: Minor Color Dullness	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar  
Condition: Color Mismatch, Paint Faded



Left A to B Pillar Beading



Right A to B Pillar



Left B Pillar Trim



Right C Pillar Trim



Right B to C Pillar Beading



Running Board Condition

Left Running Board



Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip  
Mark<5mm, Passenger Side/Stone Chip  
Mark<8mm



Structural Assessment

Chassis Condition



Apron



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror

Body: Light Scuffing < 50mm



Right Side Mirror



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel cover



Grill Condition

Scuffing > 50mm



Right A Pillar

Condition: Paint Defect



Right A to B Pillar Beading



Left B Pillar



Left B to C Pillar Beading



Right B to C Pillar



Left C Pillar

Light Scuffing < 50mm



Right Running Board



Rear Windshield



Radiator Support



Boot Floor



Cowl Top



Left Side Mirror



Right Hand Side Mirror



Antenna



Monogram



Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

Keys			
Master Key	✓		

Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	!		
Condition: Knob Fair Use Wear			
Lights			
Headlight	!	Interior Lights	✓
Left: Low Brightness lamps			
Tail Light Cluster	!	License Plate Light	✓
Left Tail Lamp: Light Scuffing < 50mm			
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓



Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<85%
Spare Tyre	<65%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE