



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 TOYOTA FORTUNER

EXR | 73,248 KM

VIN: MHFDX8FS4M0113125

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort










Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 73248 |  Specs | Yes |
|  Engine | 2.7L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | MHFDX8FS4M0113125 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls |  | Power Folding Mirrors |  |
| Rear Defogger |  | Central Armrest |  |
| Automatic Headlights |  | | |
|  Safety & Security | | | |

| | | | |
|--|---|---------------------|---|
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Exteriors | | | |
| Roof Rails | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | HID Headlights | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door |  |
| | | Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm | |

| | | | |
|-----------------------------|---|-----------------|---|
| Rear left door |  | Rear right door |  |
| Panel: Paint Chip-off < 5mm | | | |

Fenders Condition

| | | | |
|---------------------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
| Condition: Scratch < 50mm | | | |


Quarter Panels Condition

| | | | |
|---------------------------|---|---------------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
| Condition: Scratch < 50mm | | Condition: Scratch < 50mm | |

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm, Dent < 50mm | |

Hood Condition

| | |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

| | | | |
|--|---|--------------------------------------|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Passenger Side/Stone Chip Mark<8mm, Driver Side/Stone Chip Mark<5mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ! |
| | | Door Skirting: Light Scuffing < 50mm | |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover | ✓ |

| | | | |
|------------------|---|-----------------|---|
| Antenna | ✓ | Grill Condition | ✓ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| 4*4 Condition (If Applicable) | ✓ | Transmission Fluid | ✓ |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System

Condition: Available - Android Auto & Apple CarPlay



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Parking Sensors



Rear Defogger



USB Charging Port

Rear: Cigarette Lighter Missing



Power/ Manual Windows



Interiors & Luggage

| | | | |
|--------------------------------|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Cigarette Lighter: Cigarette Lighter Missing | ! |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |
| Spare Tyre | <90% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE