



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 RENAULT DUSTER

SE | 145,014 KM

VIN: VF1HSRCH4JH559989

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat

Basic Details

 Kilometers	145014	 Specs	Yes
 Engine	2.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF1HSRCH4JH559989		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger			



Safety & Security

Navigation



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Inner Beading: Rubber Crack/ Tear < 5mm



Front right door

Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm



Rear left door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm



Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm



Right Fender

Condition: Light Scuffing < 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent<30mm, Chip<5mm, Light Scuffing<50mm



Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading Beading Crack/ Tear < 5mm	!
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading Beading Crack/ Tear < 5mm	!
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Light Scuffing < 80mm	!	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓

Antenna	✓	Grill Condition Light Scuffing < 50mm	⚠
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent
Colour Faded



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Glove Box		Steering Wheel	
Sunvisor		Seat Upholstery	
Manual Seat Movement		Seat Belts	
Head Rest		Door Controls And Trim	
Grab Handle		Carpet	
Headliner		Rear View Mirror	
Toolkit			

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<85%
RHS Front Tyre	<85%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE