



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2019 NISSAN SUNNY

SV | 166,152 KM

VIN: MDHBN7AD8KG672628

Car highlights



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	166152	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MDHBN7AD8KG672628		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Comfort & Convenience			
Steering Mounted Audio Controls		Rear Defogger	



Entertainment

Bluetooth Player



USB player



Exteriors

Halogen Headlights



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Frame: Light Scuffing < 50mm

Rear left door

Panel: Scratch < 50mm, Paint Chip-off < 5mm, Dent < 30mm



Rear right door



Inner Frame: Light Scuffing < 80mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off < 5mm, Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel

Condition: Acid Marks/ Bird Dropping < 5mm



Right Quarter Panel



Condition: Light Scuffing<50mm, Chip<5mm, Low Visual Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Low Visibility
Dent < 30mm



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm



Trunk conditon

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Inner Condition: Fair Use Wear		
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Light Scuffing < 80mm
		Left C Pillar
		Scratch < 50mm
Running Board Condition		
Left Running Board		Right Running Board
Rear Left Sill Trim: Scratch < 80mm		Rear Right Sill Trim: Light Scuffing < 80mm
Windshield Condition		
Front Windshield		
Condition: Driver Side/Stone Chip		Rear Windshield
Mark<5mm, Passenger Side/Stone Chip		
Mark<8mm		
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Condition: Light Scuffing < 80mm		
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Spare Alloy/ Rim Condition		

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	!	Brake Master Cylinder	✓
Button Faded			
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Condition: Button(s) Faded

Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



Front Left: Power Window Noise/Vibration

Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	!
Steering Wheel Fair Use Wear		Left: Sunvisor LHS Minor Crack/Fair Use Wear	
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Front Left Door: Light Scuffing			
Carpet	!	Headliner	✓
Front Left Floor Mat: Smudge/Burn/Crack			
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<65%
RHS Front Tyre	<85%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE