



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 HONDA CIVIC**

**DX | 117,713 KM**

VIN: NLAFC5652HW017124

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat



Basic Details

 Kilometers	117713	 Specs	Yes
 Engine	1.6L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	NLAFC5652HW017124		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Remote Engine Start			
 <b>Exteriors</b>			

Fog Light Front	✓	Running Lights	✓
Halogen Headlights	✓		
 <b>Safety &amp; Security</b>			
Parking Sensors Rear	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	USB Charging Port	✓
USB player	✓		





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Handle: Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Handle: Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm		Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Chip<5mm			


### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

### Hood Condition

Hood	
Bonnet: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
------	---

### Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar Light Scuffing < 50mm	!
Running Board Condition			
Left Running Board Condition: Light Scuffing < 80mm	!	Right Running Board	✓
Windshield Condition			
Front Windshield Beading: Mouldings Crack/ Fair Use Wear < 50mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror Body: Chip < 5mm	!	Left Side Mirror	✓
Right Side Mirror Body: Light Scuffing < 50mm, Paint Chip-off < 5mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Grill Condition	✓

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



## Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



## Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console





Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<85%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE