



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 MAZDA 6 S | 98,949 KM

VIN: JM7GL4S34J1146066

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Traction Control	~	Airbag Curtain Shield	✓
Airbag Driver Front	~	ABS	✓
Central Locking	~	Child Safety Locking	•
্রিঃ Entertainment			
Bluetooth Player	•	USB player	•
Exteriors			


150 Point Detailed Inspection Report

Pillars Condition

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	•	Rear Windshield	•
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	•
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition Left Hand Side Mirror Body: Paint Chip-off < 5mm	(!)	Left Side Mirror	•
Right Side Mirror Body: Paint Chip-off < 5mm	(!)	Right Hand Side Mirror	•
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	•	Antenna	•



Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	•	Cruise Control	•
Infotainment Display	•	Engine Sensors	•
OBD Connector	•	Music System	✓
Camera	✓		
Lights			
Headlight	(!)	Interior Lights	✓
Left: Low Brightness lamps		·	
Tail Light Cluster	✓	Turn Signal Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	•		
🖺 Interiors & Luggage			
Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box	!

Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	•	Manual Seat Movement	•
Seat Belts	✓	Head Rest	•
Door Controls And Trim	✓	Grab Handle	•
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓
Tyres			
Tyres Tyres Condition			
	✓	Left Hand Side Rear Tyre	✓
Tyres Condition	✓	Left Hand Side Rear Tyre Right Hand Side Rear Tyre	✓
Tyres Condition Left Hand Side Front Tyre	✓✓✓		⋄
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre	✓✓		✓
Tyres Condition Left Hand Side Front Tyre Right Hand Side Front Tyre Spare Tyre	<55%		<65%

<85%

Spare Tyre

Glove Box: Minor Scuffing/Crack/Fair Use



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE