



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 HONDA CIVIC**

**DX | 111,617 KM**

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat












## Basic Details

 Kilometers	<b>111617</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>NLAFC5633LW013557</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Exteriors</b>			
Running Lights		Halogen Headlights	
 <b>Entertainment</b>			
Bluetooth Player		USB Charging Port	
Infotainment System			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## Exterior

### Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Dent < 30mm, Scratch < 50mm

Handle: Paint Chip-off < 5mm

### Fenders Condition

Left Fender



Right Fender



Condition: Dent < 30mm, Scratch < 50mm

Right Fender: Scratch < 50mm, Dent < 30mm

### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Condition: Scratch < 50mm, Dent < 30mm

### Front Bumper Condition

Front Bumper



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Trunk Condition

Trunk



### Trunk condition

Trunk



### Roof Condition

Roof



### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror		Right Hand Side Mirror	✓
Body: Scratch < 50mm	!		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim			
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	✓
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!		
Spare Alloy/ Rim Condition			
Rim: Alloy Edge/ Scuffing < 80mm	!		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

---

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

---

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

---

## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



## Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	No spare tyre		



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE