



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 GMC ACADIA

SLE | 142,213 KM

VIN: 1GKKV9ED1GJ162528

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 142213 |  Specs | Yes |
|  Engine | 3.6L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 12 Airbags |
|  Seating Capacity | 8 Seats |  Number of keys | 3 Keys |
|  VIN number | 1GKKV9ED1GJ162528 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | |
|--|---|
| Cruise Control |  |
| Steering Mounted Audio Controls |  |
| Central Armrest |  |
| Automatic Headlights |  |
|  Safety & Security | |

| | | | |
|----------------------|---|-----------------------|---|
| Parking Sensors Rear | ✓ | Reverse Camera | ✓ |
| Traction Control | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |

 **Exteriors**

| | | | |
|-------------------------|---|--------------------|---|
| Roof Rails | ✓ | Running Lights | ✓ |
| Trailer Hook / Coupling | ✓ | Halogen Headlights | ✓ |

 **Entertainment**

| | | | |
|---------------------|---|-------------------|---|
| Bluetooth Player | ✓ | USB Charging Port | ✓ |
| Infotainment System | ✓ | USB player | ✓ |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Moulding: Paint Chip-off < 5mm

Front right door



Rear left door



Panel: Scratch < 50mm, Paint Chip-off < 5mm

Rear right door



Moulding: Paint Chip-off < 5mm

Fenders Condition

Left Fender



Condition: Paint Chip-off < 5mm

Right Fender



Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm, Paint Chip-off < 5mm

Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|------------------------------|--|---|--|
| Left A Pillar | | Right A Pillar | |
| Left A to B Pillar Beading | | Right A to B Pillar Beading | |
| Right A to B Pillar | | Left B Pillar | |
| Left B Pillar Trim | | Left B to C Pillar Beading | |
| Right C Pillar Trim | | Right B to C Pillar | |
| Right B to C Pillar Beading | | Left C Pillar | |
| Beading Crack/ Tear < 5mm | | | |
| Running Board Condition | | | |
| Left Running Board | | Right Running Board | |
| | | Rear Right Sill Trim: Light Scuffing < 80mm | |
| Windshield Condition | | | |
| Front Windshield | | Rear Windshield | |
| Structural Assessment | | | |
| Chassis Condition | | Radiator Support | |
| Apron | | Boot Floor | |
| | | Door Skirting: Light Scuffing < 50mm | |
| Firewall Condition | | Cowl Top | |
| | | Beading: Crack/Fair Use Wear<50mm | |
| Head Light Support Condition | | | |
| Cowl Top | | | |
| Cowl Top | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Right Side Mirror | |
| Right Hand Side Mirror | | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | | Left Rear Alloy/ Rim | |
| Right Front Alloy/ Rim | | Right Rear Alloy/ Rim | |
| Spare Alloy/ Rim Condition | | | |
| Wheel Arch | | Wheel cover | |
| Antenna | | Grill Condition | |
| | | Light Scuffing < 50mm | |

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel

Tilt Operation: Adjuster Cover Fair Use



Wear/Missing

Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Camera



Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Air Conditioning

AC Cooling



AC Switch



Button(s) Faded

AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

| | | | |
|--|--|--|--|
| Dashboard And Instrument Panel | | Central Console | |
| Cup Holder | | Glove Box | |
| Steering Wheel | | Glove Box: Glove Box Retainer Faulty, Minor Scuffing/Crack/Fair Use Wear | |
| Steering Wheel Fair Use Wear | | | |
| Seat Upholstery | | Manual Seat Movement | |
| Seat Belts | | Head Rest | |
| Door Controls And Trim | | Grab Handle | |
| Carpet | | Headliner | |
| Trunk Floor Carpet: Wear & Tear < 80mm | | | |
| Rear View Mirror | | Toolkit | |

Tyres

Tyres Condition

| | | | |
|----------------------------|--|---------------------------|--|
| Left Hand Side Front Tyre | | Left Hand Side Rear Tyre | |
| Right Hand Side Front Tyre | | Right Hand Side Rear Tyre | |
| Spare Tyre | | | |

Tyres Depth (Remaining)

| | | | |
|----------------|------|---------------|------|
| LHS Front Tyre | <55% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <65% |
| Spare Tyre | <45% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE