



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 CHEVROLET TAHOE

LS | 63,749 KM

VIN: 1GNSK7EC5LR194580

Car highlights



Power packed

Engine size of 5.3 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort











Power driver seat




Basic Details

 Kilometers	63749	 Specs	Yes
 Engine	5.3L	 Option Type	Basic Option
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	8 Seats	 Number of keys	2 Keys
 VIN number	1GNSK7EC5LR194580		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Remote Engine Start		Automatic Headlights	
 Exteriors			

Fog Light Front	✓	Roof Rails	✓
Rear Bumper Spoiler	✓	Trailer Hook / Coupling	✓
Halogen Headlights	✓		
 Safety & Security			
Lane Departure Warning System	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Collision Warning System	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Performance			
Hill Descent Control	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door 
Weather Strip: Low Visibility Dent < 30mm

Rear left door 
Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm, Original Paint

Fenders Condition

Left Fender 
Condition: Paint Chip-off < 5mm, Low Visual Dent < 30mm


Quarter Panels Condition

Left Quarter Panel 
Condition: Original Paint

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper 
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm

Hood Condition


Hood 
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm

Trunk Condition


Trunk 
Door Trim: Scuff/ Disfiguration< 50mm


Trunk conditon

Trunk 

Front right door 
Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Original Paint

Rear right door 
Panel: Light Scuffing < 50mm, Low Visual Dent < 30mm, Original Paint

Right Fender 
Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm, Original Paint

Right Quarter Panel 
Condition: Chip<5mm, Low Visual Dent < 30mm, Original Paint

Roof Condition			
Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top Beading: Crack/Fair Use Wear<50mm	!
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		

Wheel Arch	✓	Wheel cover	✓
Grill Condition	!	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	!		
Original Paint			

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System

Condition: Available - Android Auto & Apple CarPlay



Music System



Camera



Lights

Headlight

Right: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Rear Left Floor Mat: Smudge/Burn/Crack Fair Use Wear



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%

Spare Tyre

<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE