



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN KICKS

S | 67,680 KM

### Car highlights



#### Amazing Comfort

Power driver seat



#### Tilt Steering wheel

Tilt steering wheel for extra comfort

## Basic Details

 Kilometers	<b>67680</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>3N1CP5C9XKL490455</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Steering Mounted Audio Controls	
 <b>Entertainment</b>	
USB Charging Port	
Infotainment System	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door



Rear right door

Moulding: Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Dent < 50mm, Chip< 8mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Low Visibility



Dent < 30mm

Trunk Condition

Trunk



Door Trim: Scuff/ Disfiguration< 50mm

Trunk conditon

Trunk



Roof Condition

Roof



## Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Light Scuffing			
Right C Pillar Trim		Right B to C Pillar	
Light Scuffing			
Right B to C Pillar Beading		Left C Pillar	

## Running Board Condition

Left Running Board		Right Running Board	
		Front Right Sill Trim: Low Visual Dent < 50mm	

## Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

## Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			

## Cowl Top

Cowl Top			
----------	--	--	--

## Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	

## Alloy Wheel/ Rim

Spare Alloy/ Rim Condition			
----------------------------	--	--	--

Wheel Arch		Wheel cover	
------------	--	-------------	--

Antenna		Grill Condition	
---------	--	-----------------	--

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

## Keys

Master Key		Spare Key(s)	
------------	--	--------------	--

## Door Locks

Child Safety Locking	
----------------------	--

## Dashboard

Instrument Panel	
------------------	--

## Airbags

Airbags	
---------	--

Controls		Infotainment Display	
----------	--	----------------------	--

Engine Sensors		OBD Connector	
----------------	--	---------------	--

## Music System

Rear Right Speakers: Crack/Fair Use Wear	
--	--

## Lights

Headlight		Interior Lights	
-----------	--	-----------------	--

Tail Light Cluster		License Plate Light	
--------------------	--	---------------------	--

## Air Conditioning

AC Cooling		AC Switch	
------------	--	-----------	--

AC System Leaks		Center AC Vent	
-----------------	--	----------------	--

Front Right AC Vent		Heater	
---------------------	--	--------	--

USB Charging Port		Power/ Manual Windows	
-------------------	--	-----------------------	--

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
--------------------------------	--	-----------------	--

Glove Box		Steering Wheel	
-----------	--	----------------	--

Glove Box: Minor Scuffing/Crack/Fair Use Wear		Color Faded	
---	--	-------------	--

Sunvisor		Seat Upholstery	
----------	--	-----------------	--

		Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off	
--	--	---	--

Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner			
Front Left: Light Smudge/Disfiguration, Light Scuffing	!	Rear View Mirror	✓
Toolkit	✓		

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE