



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 CHEVROLET TAHOE

LT 1 | 138,281 KM

VIN: 1GNSC6EC1FR537171

Car highlights



Power packed

Engine size of 5.3 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Airbag safety











Airbag Curtain, Airbag Driver Front

Basic Details

 Kilometers	138281	 Specs	Yes
 Engine	5.3L	 Option Type	Basic
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	9 Seats	 Number of keys	2 Keys
 VIN number	1GNSC6EC1FR537171		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk		Rear Defogger	
Central Armrest		Remote Engine Start	
Automatic Headlights			



Exteriors

Fog Light Front



Roof Rails



Rear Bumper Spoiler



Trailer Hook / Coupling



Halogen Headlights



Safety & Security

Lane Departure Warning
System



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Collision Warning System



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Hill Descent Control



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 

Exterior

Doors condition

Front left door 

Front right door
Panel: Paint Chip-off < 5mm, Light Scuffing < 
50mm, Low Visibility Dent < 30mm

Rear left door
Panel: Scratch < 50mm, Paint Chip-off < 5mm 


Rear right door
Panel: Paint Chip-off < 5mm, Light Scuffing < 
50mm


Fenders Condition

Left Fender
Condition: Paint Chip-off < 5mm 

Right Fender
Right Fender: Dent < 30mm, Paint Chip-off < 
5mm

Quarter Panels Condition


Left Quarter Panel
Condition: Scratch < 50mm 

Right Quarter Panel
Condition: Dent < 30mm, Paint Chip-off < 
5mm

Front Bumper Condition

Front Bumper 

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm 

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm, Paint Chip-off 
< 5mm

Trunk Condition

Trunk 

Trunk conditon

Trunk 

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	!
		Beading: Crack/Fair Use Wear<50mm	
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
		Right Rear Alloy/ Rim	
Right Front Alloy/ Rim	✓	Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!

Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Brake Master Cylinder	✓	Brake Disc & Brake Pad	✓
Brake Fluid	✓		
Pedals	✓		

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Button Faded



Spare Key(s)

Buttons Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster

Right Tail Lamp: Light Scuffing < 50mm



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent

Adjuster Clip Crack/Fair Use Wear



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Rear Defogger Not Working	!	USB Charging Port	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel Color Faded	!	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<85%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE