



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2017 MITSUBISHI LANCER EX**

**GLS | 149,804 KM**

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Great Parking Assistance**

Parking Sensors Rear



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**


Power driver seat











Basic Details

 Kilometers	149804	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JE3AB36A2HU708393		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest			
 <b>Exteriors</b>			
Fog Light Front		Rear Bumper Spoiler	

Halogen Headlights		
 <b>Safety &amp; Security</b>		
Parking Sensors Rear		Traction Control 
Airbag Driver Front		ABS 
Central Locking		Child Safety Locking 
 <b>Entertainment</b>		
Infotainment System		USB player 

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Handle: Scratch < 50mm		Handle: Light Scuffing < 50mm	
Rear left door		Rear right door	
Handle: Scratch < 50mm		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm		Right Fender: Dent < 30mm, Scratch < 50mm	

### Quarter Panels Condition


Left Quarter Panel		Right Quarter Panel	
Condition: Scratch < 50mm, Paint Chip-off < 5mm		Condition: Dent < 30mm, Scratch < 50mm	

### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 


### Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 

### Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm 

### Trunk conditon

Trunk 

### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading Beading Crack/ Tear < 5mm	!	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Scratch < 80mm	!	Right Running Board Condition: Light Scuffing < 80mm	!
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor Door Skirting: Light Scuffing < 50mm	!
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top Fair Use Wear/Crack<5mm	!		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/ Scuff < 50mm	!	Left Rear Alloy/ Rim	✓

Right Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/  
Scuff < 80mm



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel cover

Front Right: Face/ Scuffs < 50mm



Antenna



Grill Condition

Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel

Scratch < 50mm



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals	✓	
Suspension		
Shock Absorbers	✓	

## Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) Buttons Faded
Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Infotainment Display
Engine Sensors	✓	OBD Connector
Music System	✓	
Lights		
Headlight		
Left: Light Scuff Marks < 50mm	!	Interior Lights
Tail Light Cluster	✓	Turn Signal Lights
License Plate Light	✓	Fog Lights
Air Conditioning		
AC Cooling	✓	AC Switch
AC System Leaks	✓	Center AC Vent
Front Right AC Vent	✓	Heater
Rear Defogger	✓	USB Charging Port
Power/ Manual Windows	✓	





## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/  
Disfiguration/ Melted



### Central Console

Box: Minor Crack/Fair Use Wear/ Scuffing



### Cup Holder



### Glove Box

Glove Box: Minor Scuffing/Crack/Fair Use  
Wear



### Steering Wheel

Steering Wheel Fair Use Wear



### Sunvisor



### Seat Upholstery

Driver Seat: Minor Fair Wear/Fade off



### Manual Seat Movement



### Seat Belts



### Head Rest



### Door Controls And Trim

Front Left Door: Light Scuffing



### Grab Handle



### Carpet



### Headliner

Front Left: Light Smudge/Disfiguration, Light  
Scuffing



### Rear View Mirror



### Toolkit



## Tyres

### Tyres Condition

#### Left Hand Side Front Tyre



#### Left Hand Side Rear Tyre



#### Right Hand Side Front Tyre



#### Right Hand Side Rear Tyre



#### Spare Tyre



### Tyres Depth (Remaining)

#### LHS Front Tyre

<65%

#### LHS Rear Tyre

<75%

#### RHS Front Tyre

<65%

#### RHS Rear Tyre

<75%

#### Spare Tyre

<55%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE