



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

6 Months Warranty

This car comes with 6 months or 10,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 RENAULT SYMBOL

PE | 81,248 KM

VIN: VF14SRAB7NT040483

Car highlights



Good Tyre Condition

Tyre age less than 2 years



Running Lights

This car has a Running lights



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat


Basic Details

 Kilometers	81248	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	6 Seats	 Number of keys	1 Keys
 VIN number	VF14SRAB7NT040483		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>			
Fog Light Front	<div></div>	Running Lights	<div></div>
Halogen Headlights	<div></div>		
<div> Safety & Security</div>			
Traction Control	<div></div>	Airbag Driver Front	<div></div>
ABS	<div></div>	Central Locking	<div></div>

Child Safety Locking		
 Comfort & Convenience		
Steering Mounted Audio Controls		Rear Defogger 
 Entertainment		
Bluetooth Player		Infotainment System 
USB player		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm, Low Visibility Dent < 30mm	
-----------------	---	---	---

Rear left door Panel: Scratch < 50mm		Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	
---	---	--	---

Fenders Condition

Left Fender Condition: Light Scuffing < 50 mm		Right Fender	
--	---	--------------	---


Quarter Panels Condition

Left Quarter Panel Condition: Scratch < 50mm		Right Quarter Panel Condition: Light Scuffing<50mm	
---	---	---	---


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper Rear Bumper: Light Scuffing < 80mm, Dent < 50mm	
--	---

Hood Condition

Hood Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm	
--	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Dent, Scratch < 80mm	!	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Rear Right: Face/ Scuffs < 50mm, Edge/ Scuffs < 80mm	!
Antenna	✓	Grill Condition	✓

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights	✓
Daylight Running Lights	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console	✓
Glove Box	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓

Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	!
		Front Right Door: Fair Use Wear	
Grab Handle	✓	Carpet	!
		Front Left Floor Mat: Smudge/Burn/Crack	
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<45%	LHS Rear Tyre	<65%
RHS Front Tyre	<45%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE