



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 KIA SPORTAGE

LX | 128,808 KM

VIN: U5YPB81A7GL656125

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat


Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 128808 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Brown |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | U5YPB81A7GL656125 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|--|-----------------------------|--|
| <div> Exteriors</div> | | | |
| Fog Light Front | <div></div> | Roof Rails | <div></div> |
| Running Lights | <div></div> | Rear Bumper Spoiler | <div></div> |
| Halogen Headlights | <div></div> | | |
| <div> Comfort & Convenience</div> | | | |
| Cruise Control | <div></div> | Rear Armrest with cupholder | <div></div> |

| | | | |
|--|---|---------------------|---|
| Steering Mounted Audio Controls | ✓ | Rear Defogger | ✓ |
| Central Armrest | ✓ | | |
|  Safety & Security | | | |
| Parking Sensors Rear | ✓ | Airbag Driver Front | ✓ |
| ABS | ✓ | Central Locking | ✓ |
| Child Safety Locking | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | USB player | ✓ |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|--|---|------------------------------|---|
| Front left door |  | Front right door |  |
| | | Panel: Light Scuffing < 50mm | |
| Rear left door |  | Rear right door |  |
| Panel: Dent < 30mm, Paint Chip-off < 5mm | | Handle: Scratch < 50mm | |

Fenders Condition

| | | | |
|---|---|------------------------------|---|
| Left Fender | | Right Fender | |
| Condition: Scratch < 50mm, Paint Chip-off < 5mm |  | Right Fender: Scratch < 50mm |  |

Quarter Panels Condition

| | | | |
|--|---|---------------------|---|
| Left Quarter Panel | | Right Quarter Panel |  |
| Condition: Dent < 30mm, Scratch < 50mm |  | | |

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|--------------------------|---|
| Rear Bumper |  |
| Rear Bumper: Dent < 50mm | |

Hood Condition

| | |
|---|---|
| Hood |  |
| Bonnet: Acid Marks/ Bird Dropping < 5mm | |





Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Pillars Condition

| | | | |
|----------------------------|---|-----------------------------|---|
| Left A Pillar |  | Right A Pillar |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

| | | | |
|---|---|-------------------------------|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Passenger Side/Stone Chip Mark<8mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ! | Left Side Mirror | ✓ |
| Body: Paint Chip-off < 5mm | | | |
| Right Side Mirror | ! | Right Hand Side Mirror | ✓ |
| Body: Scratch < 50mm | | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ! |
| | | Rim: Alloy Face/ Scuff < 50mm | |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ! |
| | | Rim: Alloy Face/ Scuff < 50mm | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ! | Monogram | ✓ |
| Light Scuffing < 50mm | | | |

| | | | |
|------------------|---|-------|---|
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | | | |
| Scratch < 50mm | ! | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|------|--|--|--|
| Keys | | | |
|------|--|--|--|

| | | | |
|----------------------|---|-------------------------|---|
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--|---|---|---|
| Dashboard And Instrument Panel | ✓ | Central Console Box: Minor Crack/Fair Use Wear/ Scuffing | ! |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel Steering Wheel Fair Use Wear | ! | Sunvisor | ✓ |

| | | | |
|--|---|----------------------|---|
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ! | Grab Handle | ✓ |
| Front Left Door: Light Scuffing/ Disfiguration | | | |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <55% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <75% |
| Spare Tyre | <75% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE