



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2014 TOYOTA FJ CRUISER GXR | 146,931 KM

VIN: JTEBU11F1EK190503

# **Car highlights**



### **Power packed**

Engine size of 4.0 Litres & 6.0 cylinders



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**

Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat

#### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.




Central Locking	<b>✓</b>	Child Safety Locking	~
Performance			
Differential Locks	<b>✓</b>		
□a Entertainment			
Bluetooth Player	<b>~</b>	Infotainment System	<b>✓</b>
USB player	<b>✓</b>		
Exteriors			
Halogen Headlights	<b>✓</b>		

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	<b>✓</b>	Right A Pillar	<b>✓</b>
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board  Rear Right Sill Trim: Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Radiator Support	<b>✓</b>
Apron	<b>✓</b>	Boot Floor	<b>✓</b>
Firewall Condition	<b>✓</b>	Cowl Top	<b>✓</b>
Head Light Support Condition	<b>✓</b>		
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	!
Right Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel Arch	<b>✓</b>	Wheel cover	<b>✓</b>
Antenna	<b>✓</b>	Grill Condition Light Scuffing < 50mm	!



Keys  Master Key	•	Spare Key(s) Fair Use Wear	(!)
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Cruise Control	<b>✓</b>	Infotainment Display	<b>✓</b>
Engine Sensors	<b>✓</b>	OBD Connector	<b>✓</b>
Music System	<b>✓</b>		
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>~</b>
Tail Light Cluster	<b>✓</b>	License Plate Light	<b>✓</b>
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>~</b>
Front Right AC Vent	<b>✓</b>	Heater	•
Rear Defogger Not Working	!	USB Charging Port	<b>✓</b>
Power/ Manual Windows	<b>✓</b>		
Interiors & Luggage			
Dashboard And Instrument Panel	<b>✓</b>	Central Console	<b>✓</b>
Cup Holder	<b>✓</b>	Glove Box	<b>✓</b>
Steering Wheel	<b>✓</b>	Sunvisor	<b>✓</b>
Seat Upholstery  Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	<b>✓</b>
Seat Belts	•	Head Rest	•

Door Controls And Trim	•	Grab Handle	<b>✓</b>
Carpet Front Left Floor Mat: Smudge/Burn/Crac	k !	Headliner	•
Rear View Mirror	<b>✓</b>	Toolkit	<b>✓</b>
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	<b>✓</b>		
Tyres Depth (Remaining)			
Tyres Deptit (Itemailing)			
LHS Front Tyre	<90%	LHS Rear Tyre	<90%
	<90% <90%	LHS Rear Tyre RHS Rear Tyre	<90% <90%



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE