



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 MAZDA 6

S | 47,341 KM

VIN: JM7GL4S3XM1430192

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	47341	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM7GL4S3XM1430192		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 Safety & Security	

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



Exteriors

Running Lights		LED Headlights	
----------------	---	----------------	---



Entertainment

Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm



Rear left door

Panel: Dent < 30mm, Scratch < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender

Condition: Light Scuffing < 50 mm



Condition: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel

Condition: Acid Marks/ Bird Dropping < 5mm, Repaired and Painted

Right Quarter Panel

Condition: Light Scuffing<50mm, Chip<5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm

Right Quarter Panel

Condition: Light Scuffing<50mm, Chip<5mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm

Right Quarter Panel

Condition: Light Scuffing<50mm, Chip<5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof			
Pillars Condition			
Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board Condition: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror Body: Paint Chip-off < 5mm		Left Side Mirror	
Right Side Mirror Body: Scratch < 50mm		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm		Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	
Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			

Wheel Arch	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			!
Scratch < 50mm			

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

擐 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys

Master Key 

Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Music System 

Camera



Lights

Headlight 

Interior Lights 

Tail Light Cluster 

Turn Signal Lights 

Daylight Running Lights 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent 

Front Right AC Vent 

Heater 

Rear Blower Switch 

Rear Defogger 

USB Charging Port 

Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear	!	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Rear Left Seat: Minor Smudge/ Crack	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Rear Left Door: Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE