



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 MITSUBISHI PAJERO

GLS LOWLINE | 56,706 KM

VIN: JE4MR52N1LJ712776

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	56706	 Specs	Yes
 Engine	3.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Beige
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JE4MR52N1LJ712776		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 Exteriors	

Fog Light Front		Running Lights	
Halogen Headlights		HID Headlights	
Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
Performance			
Differential Locks			
Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Moulding: Paint Chip-off < 5mm

Rear left door



Rear right door



Moulding: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Scuffing > 80mm

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Low Visibility



Dent < 30mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch			
Front Right: minor imperfection	!	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram
Light Scuffing < 50mm



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key		Spare Key(s)	
------------	--	--------------	--

Door Locks

Child Safety Locking	
----------------------	--

Dashboard

Instrument Panel	
------------------	--

Airbags

Airbags	
---------	--

Controls

Fuel Door Release: minor imperfection		Cruise Control	
---------------------------------------	--	----------------	--

Infotainment Display		Engine Sensors	
----------------------	--	----------------	--

OBD Connector		Music System	
---------------	--	--------------	--

Lights

Headlight		Interior Lights	
-----------	--	-----------------	--

Tail Light Cluster		Turn Signal Lights	
--------------------	--	--------------------	--

Daylight Running Lights		License Plate Light	
-------------------------	--	---------------------	--

Fog Lights	
------------	--

Left Fog Light: Low Brightness lamps	
--------------------------------------	--

Air Conditioning

AC Cooling		AC Switch	
------------	--	-----------	--

AC System Leaks		Center AC Vent	
-----------------	--	----------------	--

Front Right AC Vent		Heater	
---------------------	--	--------	--

Rear Blower Switch		Rear Left AC Vent	
--------------------	--	-------------------	--

Parking Sensors		Rear Defogger	
-----------------	--	---------------	--

USB Charging Port		Power/ Manual Windows	
-------------------	--	-----------------------	--

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
--------------------------------	--	-----------------	--

Cigarette Lighter: Cigarette Lighter Missing	
--	--

Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	!
Steering Wheel Fair Use Wear		Left: Sunvisor LHS Minor Smudge, Sunvisor RHS Minor Smudge, RHS Sunvisor Holder Crack/ Broken	
Seat Upholstery	!	Manual Seat Movement	✓
Rear Left Seat: Minor Smudge/ Crack			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Front Right Door: Light Scuffing			
Carpet	✓	Headliner	!
		Rear Left: Smudge/Disfiguration	
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<85%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE