



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 NISSAN SENTRA**

**S | 136,678 KM**

**VIN: MNTAB7A99G6007937**

### **Car highlights**



#### **Amazing Comfort**

Power driver seat



#### **Tilt Steering wheel**

Tilt steering wheel for extra comfort

## Basic Details

 Kilometers	<b>136678</b>	 Specs	<b>Yes</b>
 Engine	<b>1.8L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Silver</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MNTAB7A99G6007937</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Cruise Control	
 Steering Mounted Audio Controls	
 <b>Safety &amp; Security</b>	
Navigation	
 Reverse Camera	
 <b>Entertainment</b>	

USB Charging Port



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Acid Marks/ Bird Dropping < 5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Condition: Low Visual Dent<30mm, Light Scuffing<50mm

Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
		Front Right Sill Trim: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel Arch		Wheel cover	
Grill Condition			
Scuffing > 50mm		Monogram	
Window Glass		Wiper	

## Panel Condition

Rear Trunk Panel



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Camera



Lights

Headlight



Left: Low Brightness lamps

Interior Lights



Tail Light Cluster



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



## **Interiors & Luggage**

Dashboard And Instrument Panel

Dashboard Upholstery: Scuffing/  
Disfigurement/ Melted > 80 mm



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	!
Door Controls And Trim	✓	Driver Seat: Fair Use Wear	
Carpet	!	Grab Handle	✓
Front Left Floor Mat: Floor Mat Lock Damage		Headliner	!
Rear View Mirror	✓	Front Left: Light Smudge/Disfiguration	
		Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE