



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2014 HYUNDAI ELANTRA

GL | 115,028 KM

VIN: KMHDG41E9EU833385

Car highlights



Great condition

Car has low imperfections



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



Amazing Comfort
















Power driver seat



Airbag safety










Airbag Driver Front

Basic Details

 Kilometers	115028	 Specs	Yes
 Engine	1.8L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KMHDG41E9EU833385		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div></div> <div>Exteriors</div>					
Fog Light Front		<div></div>	Halogen Headlights		<div></div>
<div></div> <div>Comfort & Convenience</div>					
Rear Armrest with cupholder		<div></div>	Steering Mounted Audio Controls		<div></div>
Rear Defogger		<div></div>	Central Armrest		<div></div>
Steering Column Adjuster		<div></div>			



Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Parking Sensors



Rear Defogger



USB Charging Port



Rear Entertainment



Power/ Manual Windows



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<45%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE