



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 MG ZS**

**TROPHY | 16,350 KM**

VIN: LSJW74C96MZ063997

## **Car highlights**



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**












Power driver seat





Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 16350             |  Specs             | Yes                  |
|  Engine           | 1.3L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | LSJW74C96MZ063997 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                       |   |
|--|---|-----------------------|---|
| <div> Safety &amp; Security</div> |   |                       |   |
| 360 degree Camera  |  | Parking Sensors Rear  |  |
| Reverse Camera   |  | Blind Spot Monitor    |  |
| Traction Control   |  | Front Camera          |  |
| Side Camera  |  | Airbag Curtain Shield |  |
| ABS  |  | Central Locking       |  |

|  |   |                                 |   |
|--|---|---------------------------------|---|
| Child Safety Locking   | ✓ |                                 |   |
| <div> Exteriors</div>                 |   |                                 |   |
| Fog Light Front  | ✓ | Roof Rails                      | ✓ |
| Running Lights   | ✓ | HID Headlights                  | ✓ |
| <div> Comfort &amp; Convenience</div> |   |                                 |   |
| Cruise Control   | ✓ | Steering Mounted Audio Controls | ✓ |
| Power Folding Mirrors  | ✓ | Rear Defogger                   | ✓ |
| Central Armrest  | ✓ | Automatic Headlights            | ✓ |
| <div> Performance</div>               |   |                                 |   |
| Hill Descent Control   | ✓ |                                 |   |
| <div> Entertainment</div>           |   |                                 |   |
| Bluetooth Player   | ✓ | Apple Play                      | ✓ |
| Android Auto Play  | ✓ | USB Charging Port               | ✓ |
| Infotainment System  | ✓ | USB player                      | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |   |                  |   |
|-----------------|---|------------------|---|
| Front left door |  | Front right door |  |
|-----------------|---|------------------|---|

|                |   |                 |   |
|----------------|---|-----------------|---|
| Rear left door |  | Rear right door |  |
|----------------|---|-----------------|---|

Fenders Condition

|             |   |              |   |
|-------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
|-------------|---|--------------|---|


Quarter Panels Condition

|                    |   |                     |   |
|--------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|---|---------------------|---|

Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

|                                    |   |
|------------------------------------|---|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |   |

Hood Condition

|      |   |
|------|---|
| Hood |  |
|------|---|

Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

Pillars Condition

|               |   |                |   |
|---------------|---|----------------|---|
| Left A Pillar |  | Right A Pillar |  |
|---------------|---|----------------|---|

|                            |   |                             |   |
|----------------------------|---|-----------------------------|---|
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
|----------------------------|---|-----------------------------|---|

|                     |   |               |   |
|---------------------|---|---------------|---|
| Right A to B Pillar |  | Left B Pillar |  |
|---------------------|---|---------------|---|

|                                       |   |  |   |
|---------------------------------------|---|--|---|
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading               | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar                      | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                            | ✓ |
| Running Board Condition               |   |  |   |
| Left Running Board                    | ✓ | Right Running Board                      | ✓ |
| Sunroof Glass Condition (If Equipped) |   |  |   |
| Sun Roof Glass                        | ✓ |  |   |
| Windshield Condition                  |   |  |   |
| Front Windshield                      | ✓ | Rear Windshield                          | ✓ |
| Structural Assessment                 |   |  |   |
| Chassis Condition                     | ✓ | Radiator Support                         | ✓ |
| Apron                                 | ✓ | Boot Floor                               | ✓ |
| Firewall Condition                    | ✓ | Cowl Top                                 | ✓ |
| Head Light Support Condition          | ✓ |  |   |
| Cowl Top                              |   |  |   |
| Cowl Top                              | ✓ |  |   |
| Rear View Mirror Condition            |   |  |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror                         | ✓ |
| Right Side Mirror                     | ✓ | Right Hand Side Mirror                   | ✓ |
| Alloy Wheel/ Rim                      |   |  |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim                     | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim                    | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |  |   |
| Antenna                               | ✓ | Grill Condition<br>Light Scuffing < 50mm | ⓘ |
| Monogram                              | ✓ | Window Glass                             | ✓ |
| Wiper                                 | ✓ |  |   |
| Panel Condition                       |   |  |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

|                         |   |                     |   |
|-------------------------|---|---------------------|---|
| Child Safety Locking    | ✓ |                     |   |
| Dashboard               |   |                     |   |
| Instrument Panel        | ✓ |                     |   |
| Airbags                 |   |                     |   |
| Airbags                 | ✓ |                     |   |
| Controls                | ✓ | Cruise Control      | ✓ |
| Infotainment Display    | ✓ | Engine Sensors      | ✓ |
| OBD Connector           | ✓ | Radar (If Equipped) | ✓ |
| Music System            | ✓ |                     |   |
| Sunroof Operation       |   |                     |   |
| Sunroof                 | ✓ |                     |   |
| Camera                  | ✓ |                     |   |
| Lights                  |   |                     |   |
| Headlight               | ✓ | Interior Lights     | ✓ |
| Tail Light Cluster      | ✓ | Turn Signal Lights  | ✓ |
| Daylight Running Lights | ✓ | License Plate Light | ✓ |
| Fog Lights              | ✓ |                     |   |
| Air Conditioning        |   |                     |   |
| AC Cooling              | ✓ | AC Switch           | ✓ |
| AC System Leaks         | ✓ | Center AC Vent      | ✓ |
| Front Right AC Vent     | ✓ | Heater              | ✓ |
| Rear Blower Switch      | ✓ |                     |   |
| Rear Defogger           | ✓ | USB Charging Port   | ✓ |
| Power/ Manual Windows   | ✓ | Seat Heaters        | ✓ |



|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Glove Box                      | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Grab Handle                    | ✓ | Carpet                 | ✓ |
| Headliner                      | ✓ | Rear View Mirror       | ✓ |
| Toolkit                        | ✓ |                        |   |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Tyres Depth (Remaining)    |      |                           |      |
| LHS Front Tyre             | <65% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <65% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE