



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2014 HYUNDAI SONATA

GLS | 96,861 KM

VIN: KMHEB41CSEA632002

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	96861	 Specs	Yes
 Engine	2.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KMHEB41CXEA632002		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Rear Defogger		Central Armrest	

Automatic Headlights



Steering Column Adjuster



Performance

Paddle Shift



Safety & Security

Parking Sensors Rear



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Light Scuffing < 50mm

Rear left door



Rear right door



Handle: Paint Chip-off < 5mm

Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Paint



Right Fender



Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Chip<5mm, Light Scuffing<50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip<



8mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off



< 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

Running Board Condition

Left Running Board		Right Running Board	
		Condition: Light Scuffing < 80mm	

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

Windshield Condition

Front Windshield

Beading: Mouldings Crack/ Fair Use Wear < 50mm		Rear Windshield	
--	--	-----------------	--

Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			

Cowl Top

Cowl Top	
----------	--

Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
-----------------------	--	------------------	--

Right Side Mirror

Body: minor imperfection	
--------------------------	--

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm		Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	

Right Front Alloy/ Rim	Right Rear Alloy/ Rim
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/ Scuff < 80mm	!
Spare Alloy/ Rim Condition	✓
Wheel cover	✓
Monogram	✓
Wiper	✓
Panel Condition	
Rear Trunk Panel	✓

⌚ Engine & Transmission

Engine	
Engine Body	✓
Engine Oil (Condition & Level)	✓
Radiator Condition	✓
Engine Performance	✓
Exhaust System	✓
Radiator Coolant	✓
Battery	
Battery Terminal & Tightness	✓
Fuel System	
Fuel Tank	✓
Transmission Operation	
Gear Shifting	✓
Drive Axle	
Rear Axle: minor imperfection	!
Gear shift	✓
Transmission Fluid	✓

⌚ Steering, Suspension & Brakes

Steering	
Steering wheel	✓
Brake System	
Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓
Brake Fluid	✓

Pedals



Suspension



Shock Absorbers

Electricals, Controls & Lights

Keys



Master Key

Door Locks



Child Safety Locking

Dashboard



Instrument Panel

Airbags



Airbags

Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent
minor imperfection



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ 

Fair Use Wear

Central Console



Gear Shift Knob: minor imperfection

Cup Holder



Glove Box



Steering Wheel



Color Faded

Sunvisor



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use 

Wear/ Tears

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE