



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 JEEP GRAND CHEROKEE

LAREDO | 76,910 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera &
more



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 76910 |  Specs | Yes |
|  Engine | 3.6L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Rear Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Fabric Trim |  Number of Airbags | 7 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 3 Keys |
|  VIN number | 1C4RJEAG3KC754606 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Comfort & Convenience | |
|--|---|
| Climate Control AC |  |
| Rear Armrest with cupholder |  |
| Power Folding Mirrors |  |
| Central Armrest |  |
| Steering Column Adjuster |  |
| Cruise Control |  |
| Steering Mounted Audio Controls |  |
| Rear Defogger |  |
| Automatic Headlights |  |



Exteriors

| | | | |
|-----------------|--|---------------------|--|
| Fog Light Front | | Roof Rails | |
| Running Lights | | Rear Bumper Spoiler | |
| HID Headlights | | | |



Performance

| | | |
|--------------|--|--|
| Paddle Shift | | |
|--------------|--|--|



Safety & Security

| | | | |
|-----------------------|--|-----------------------|--|
| Parking Sensors Front | | Parking Sensors Rear | |
| Reverse Camera | | Blind Spot Monitor | |
| Traction Control | | Airbag Curtain Shield | |
| Airbag Knees | | Airbag Driver Front | |
| ABS | | Central Locking | |
| Child Safety Locking | | | |



Entertainment

| | | | |
|------------------|--|---------------------|--|
| Bluetooth Player | | Infotainment System | |
| USB player | | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Frame: Light Scuffing < 50mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Scratch < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm,



Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



| | | | |
|-------------------------------------|--|-----------------------------|--|
| Left A to B Pillar Beading | | Right A to B Pillar Beading | |
| Right A to B Pillar | | Left B Pillar | |
| Left B Pillar Trim | | Left B to C Pillar Beading | |
| Right C Pillar Trim | | Right B to C Pillar | |
| Right B to C Pillar Beading | | Left C Pillar | |
| Running Board Condition | | | |
| Left Running Board | | Right Running Board | |
| Windshield Condition | | | |
| Front Windshield | | | |
| Condition: Driver Side/Stone Chip | | | |
| Mark<5mm, Passenger Side/Stone Chip | | Rear Windshield | |
| Mark<8mm | | | |
| Structural Assessment | | | |
| Chassis Condition | | Radiator Support | |
| Apron | | Boot Floor | |
| Firewall Condition | | Cowl Top | |
| Head Light Support Condition | | | |
| Cowl Top | | | |
| Cowl Top | | | |
| Fair Use Wear/Crack<5mm | | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | | Left Side Mirror | |
| Right Side Mirror | | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | | Left Rear Alloy/ Rim | |
| Right Front Alloy/ Rim | | Right Rear Alloy/ Rim | |
| Spare Alloy/ Rim Condition | | | |
| Wheel Arch | | Wheel cover | |
| Grill Condition | | | |
| Light Scuffing < 50mm | | Monogram | |

Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls



Cruise Control



Infotainment Display 

Engine Sensors



OBD Connector 

Radar (If Equipped)



Music System 

Camera



Lights

Headlight 

Interior Lights



Tail Light Cluster 

Daylight Running Lights



License Plate Light 

Fog Lights



Air Conditioning

AC Cooling 

AC Switch



AC System Leaks 

Center AC Vent



Front Right AC Vent 

Heater



Rear Blower Switch 

Parking Sensors 

Rear Defogger



USB Charging Port 

Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted 

Central Console



Cigarette Lighter: Cigarette Lighter Missing

Cup Holder 

Glove Box



| | | | |
|--|---|--------------------------|---|
| Steering Wheel | ! | Sunvisor | ✓ |
| Steering Wheel Fair Use Wear | | | |
| Seat Upholstery | ! | Manual Seat Movement | ✓ |
| Driver Seat: Minor Smudge/ Cracks | | | |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ! | Grab Handle | ✓ |
| Front Right Door: Light Scuffing/Disfiguration | | | |
| Carpet | ✓ | Headliner | ! |
| | | Rear Left: Fair Use Wear | |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Tyres Depth (Remaining)

| | | | |
|----------------|------|---------------|------|
| LHS Front Tyre | <90% | LHS Rear Tyre | <90% |
| RHS Front Tyre | <90% | RHS Rear Tyre | <90% |
| Spare Tyre | <45% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE