



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2018 NISSAN KICKS**

**S | 43,721 KM**

VIN: 3N1CP5C91JL488379

## **Car highlights**



### **Low Mileage**

This car has been driven less than 15,000 km  
a year



### **Bluetooth**

Enjoy your drive with bluetooth



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 43721             |  Specs             | Yes                  |
|  Engine           | 1.6L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | 3N1CP5C91JL488379 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |  |                                                                                                |                     |  |                                                                                                  |
|----------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|---------------------|--|--------------------------------------------------------------------------------------------------|
| <div> Exteriors</div>             |  |                                                                                                |                     |  |                                                                                                  |
| Roof Rails                                                                                                           |  | <div></div> | Halogen Headlights  |  | <div></div> |
| <div> Safety &amp; Security</div> |  |                                                                                                |                     |  |                                                                                                  |
| Traction Control                                                                                                     |  | <div></div> | Airbag Driver Front |  | <div></div> |
| ABS                                                                                                                  |  | <div></div> | Central Locking     |  | <div></div> |
| Child Safety Locking                                                                                                 |  | <div></div> |                     |  |                                                                                                  |



### Comfort & Convenience

Steering Mounted Audio  
Controls



Rear Defogger



Steering Column Adjuster



### Entertainment

Bluetooth Player



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                  |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door |  |
|-----------------|-----------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|

|                |                                                                                   |                             |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door             |  |
|                |                                                                                   | Panel: Paint Chip-off < 5mm |                                                                                     |

### Fenders Condition

|                                   |                                                                                   |              |                                                                                     |
|-----------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender                       |                                                                                   | Right Fender |  |
| Condition: Low Visual Dent < 30mm |  |              |                                                                                     |

### Quarter Panels Condition

|                    |                                                                                   |                                   |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|-----------------------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel               |  |
|                    |                                                                                   | Condition: Low Visual Dent < 30mm |                                                                                     |

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Hood                         |                                                                                     |
| Bonnet: Paint Chip-off < 5mm |  |

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|               |                                                                                     |                |                                                                                       |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|
| Left A Pillar |  | Right A Pillar |  |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|

|                              |   |                            |   |
|------------------------------|---|----------------------------|---|
| Right A to B Pillar          | ✓ | Left B Pillar              | ✓ |
| Left B Pillar Trim           | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim          | ✓ | Right B to C Pillar        | ✓ |
| Right B to C Pillar Beading  | ✓ | Left C Pillar              | ✓ |
| Running Board Condition      |   |                            |   |
| Left Running Board           | ✓ | Right Running Board        | ✓ |
| Windshield Condition         |   |                            |   |
| Front Windshield             | ✓ | Rear Windshield            | ✓ |
| Structural Assessment        |   |                            |   |
| Chassis Condition            | ✓ | Radiator Support           | ✓ |
| Apron                        | ✓ | Boot Floor                 | ✓ |
| Firewall Condition           | ✓ | Cowl Top                   | ✓ |
| Head Light Support Condition | ✓ |                            |   |
| Cowl Top                     |   |                            |   |
| Cowl Top                     | ✓ |                            |   |
| Rear View Mirror Condition   |   |                            |   |
| Left Hand Side Mirror        | ✓ | Left Side Mirror           | ✓ |
| Right Side Mirror            | ✓ |                            |   |
| Alloy Wheel/ Rim             |   |                            |   |
| Spare Alloy/ Rim Condition   | ✓ |                            |   |
| Wheel Arch                   | ✓ | Wheel cover                | ✓ |
| Antenna                      | ✓ | Grill Condition            | ✓ |
| Monogram                     | ✓ | Window Glass               | ✓ |
| Wiper                        | ✓ |                            |   |
| Panel Condition              |   |                            |   |
| Rear Trunk Panel             | ✓ |                            |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

|                     |   |                       |   |
|---------------------|---|-----------------------|---|
| Instrument Panel    | ✓ |                       |   |
| Airbags             |   |                       |   |
| Airbags             | ✓ |                       |   |
| Controls            | ✓ | Infotainment Display  | ✓ |
| Engine Sensors      | ✓ | OBD Connector         | ✓ |
| Music System        | ✓ |                       |   |
| Lights              |   |                       |   |
| Headlight           | ✓ | Interior Lights       | ✓ |
| Tail Light Cluster  | ✓ | License Plate Light   | ✓ |
| Air Conditioning    |   |                       |   |
| AC Cooling          | ✓ | AC Switch             | ✓ |
| AC System Leaks     | ✓ | Center AC Vent        | ✓ |
| Front Right AC Vent | ✓ | Heater                | ✓ |
| USB Charging Port   | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Glove Box                      | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Grab Handle                    | ✓ | Carpet                 | ✓ |
| Headliner                      | ✓ | Rear View Mirror       | ✓ |
| Toolkit                        | ✓ |                        |   |



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<75%

RHS Front Tyre

<85%

RHS Rear Tyre

<75%

Spare Tyre

<65%



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE