



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2020 KIA CERATO**

**LX | 136,121 KM**

## **Car highlights**



### **Running Lights**

This car has a Running lights



### **Bluetooth**

Enjoy your drive with bluetooth



### **Music System**
















Enjoy your drive with music system



### **Amazing Comfort**





Power driver seat

Basic Details

 Kilometers	136121	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KNAF14169L5891721		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Running Lights			
Halogen Headlights			
 Safety & Security			
Traction Control			
Airbag Driver Front			
ABS			
Child Safety Locking			
 Comfort & Convenience			

Steering Mounted Audio Controls	✓	Rear Defogger	✓
Central Armrest	✓	Steering Column Adjuster	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 

## Exterior

### Doors condition

Front left door		Front right door Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door Panel: Scuffing > 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm	

### Fenders Condition

Left Fender Condition: Scratch < 50mm, Paint Chip-off < 5mm		Right Fender Right Fender: Scratch < 50mm, Paint Chip-off < 5mm	
--	---	--	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm	
--------------------	---	---	---

### Front Bumper Condition

Front Bumper	
--------------	---


### Rear Bumper Condition

Rear Bumper Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Chip< 8mm	
---	---

### Hood Condition

Hood Bonnet: Scuffing > 50mm, Low Visibility Dent < 30mm, Paint Chip-off < 5mm	
---	---

### Trunk Condition

Trunk Door Trim: Light Scuffing < 50mm	
---	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	!
		Front Right: Edge/ Scuffs < 80mm	
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram



Window Glass



Wiper



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

## Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Light Scuffing/ Disfiguration/Melted	!	Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery			
Driver Seat: Smudge/ Cracks	!	Manual Seat Movement	✓



Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet		Headliner	
Front Left Floor Mat: Floor Mat Lock Damage, Smudge/Burn/Crack	!	Front Left: Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
---------------------------	---	--------------------------	---

Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
----------------------------	---	---------------------------	---

Spare Tyre	✓
------------	---

### Tyres Depth (Remaining)

LHS Front Tyre	<55%	LHS Rear Tyre	<75%
----------------	------	---------------	------

RHS Front Tyre	<65%	RHS Rear Tyre	<65%
----------------	------	---------------	------

Spare Tyre	<65%
------------	------



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE