



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2019 TOYOTA YARIS E | 116,754 KM

## **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



#### **Bluetooth**


Enjoy your drive with bluetooth



### **Amazing Comfort**


Power driver seat

#### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.





### **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality




Right A to B Pillar		Left B Pillar	
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board  Condition: Dent > 50mm	(!)
Windshield Condition			
Front Windshield Condition: Passenger Side/Light Scuffing<50mm, Driver Side/Stone Chip Mark<5mm	(!)	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	~
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	•		
Wheel cover	<b>~</b>	Antenna	<b>~</b>
Grill Condition Light Scuffing < 50mm	!	Monogram	<b>~</b>
Window Glass	<b>✓</b>	Wiper	

# **Engine & Transmission**

Engine







Tyres Condition			
Left Hand Side Front Tyre	~	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	~		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE