



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 MITSUBISHI ATTRAGE

GLX MIDLINE | 94,933 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio controls



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	94933	 Specs	Yes
 Engine	1.2L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MMDAF26J9LH007468		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors					
Fog Light Front			Halogen Headlights		
 Comfort & Convenience					
Cruise Control			Rear Armrest with cupholder		
Steering Mounted Audio Controls			Rear Defogger		
Steering Column Adjuster					



Safety & Security

Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Light Scuffing < 50mm	

Rear left door		Rear right door	
		Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Condition: Light Scuffing	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Chip< 8mm, Light Scuffing < 80mm, Dent < 50mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)

Buttons Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	⚠	Cruise Control	✓
Horn: Colour Low Brightness			
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	⚠
Steering Wheel			
Steering Wheel Fair Use Wear	⚠	Sunvisor	✓
Seat Upholstery			
Driver Seat: Minor Smudge/ Cracks	⚠	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim			
Front Left Door: Light Scuffing	⚠	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<55%

RHS Front Tyre

<75%

RHS Rear Tyre

<55%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE