



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2017 TOYOTA RAV4 GXR | 62,617 KM

# **Car highlights**



### **Great condition**

Car has low imperfections



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Bluetooth**


Enjoy your drive with bluetooth



## **Amazing Comfort**


Power driver seat

### **Basic Details**



## **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Fog Light Front	<b>✓</b>	Roof Rails	<b>✓</b>
Rear Bumper Spoiler	<b>✓</b>	Halogen Headlights	<b>✓</b>
Safety & Security			
Parking Sensors Rear	<b>~</b>	Reverse Camera	•
Traction Control	<b>✓</b>	Airbag Driver Front	<b>~</b>
ABS	<b>✓</b>	Central Locking	<b>✓</b>
Child Safety Locking	<b>✓</b>		
Performance			
Hill Descent Control	<b>✓</b>	Differential Locks	•
↓ □ ■ Entertainment ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■			
Bluetooth Player	<b>~</b>	Infotainment System	<b>~</b>
USB player			

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	<b>✓</b>		
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>~</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>~</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>~</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	<b>✓</b>	Right Rear Alloy/ Rim	<b>✓</b>
Spare Alloy/ Rim Condition	<b>✓</b>		
Antenna	<b>✓</b>	Grill Condition	<b>✓</b>
Monogram	<b>✓</b>	Window Glass	<b>✓</b>
Wiper	<b>✓</b>		
Panel Condition			
Rear Trunk Panel	<b>✓</b>		

Lingine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>✓</b>
4*4 Condition (If Applicable)	<b>✓</b>	Transmission Fluid	<b>✓</b>
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>	Spare Key(s)	<b>✓</b>
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		
Controls	<b>✓</b>	Cruise Control	<b>✓</b>

Infotainment Display	<b>✓</b>	OBD Connector	•
Music System	<b>✓</b>		
Sunroof Operation			
Sunroof	<b>✓</b>		
Camera	<b>✓</b>		
Lights			
Headlight	<b>✓</b>	Interior Lights	<b>✓</b>
Tail Light Cluster Right Tail Lamp: Crack / Fair Use Wear < 5mm	(!)	License Plate Light	<b>✓</b>
Fog Lights	<b>✓</b>		
Air Conditioning			
AC Cooling	<b>✓</b>	AC Switch	<b>✓</b>
AC System Leaks	<b>✓</b>	Center AC Vent	<b>✓</b>
Front Right AC Vent	<b>✓</b>	Heater	<b>✓</b>
Rear Defogger	<b>✓</b>	USB Charging Port	<b>✓</b>
Power/ Manual Windows	<b>✓</b>		
Interiors & Luggage			
Dashboard And Instrument Panel	<b>✓</b>	Central Console	<b>✓</b>
Cup Holder	<b>✓</b>	Glove Box	<b>✓</b>
Steering Wheel	<b>✓</b>	Sunvisor	<b>✓</b>
Seat Upholstery	<b>✓</b>	Manual Seat Movement	<b>✓</b>
Seat Belts	<b>✓</b>	Head Rest	•
Door Controls And Trim Front Right Door: Light Scuffing/Disfiguration	(!)	Grab Handle	<b>✓</b>

Carpet	<b>✓</b>	Headliner	•
Rear View Mirror	•	Toolkit	•
Tyres			
Tyres Condition			
Left Hand Side Front Tyre	<b>✓</b>	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	<b>✓</b>	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	<b>✓</b>		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	<75%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE