



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 MITSUBISHI ASX

GLX MID | 48,876 KM

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat



Basic Details

 Kilometers	48876	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JE4LP21U8LU702382		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Steering Column Adjuster			
 Exteriors			

Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
HID Headlights	✓		
 Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	✓
Traction Control	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓

Navigation System

Condition: Available - Android Auto & Apple CarPlay



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner




Rear View Mirror



Toolkit



Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<55%
RHS Front Tyre	<55%	RHS Rear Tyre	<55%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE