



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 NISSAN ALTIMA

SV | 44,726 KM

VIN: 1N4AL3A98JC127658

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	44726	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1N4AL3A98JC127658		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Remote Engine Start	

Automatic Headlights



Steering Column Adjuster



Safety & Security

Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Entertainment

Bluetooth Player



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board Condition: Light Scuffing < 80mm	
Windshield Condition			
Front Windshield			
Beading: Mouldings Crack/ Fair Use Wear < 50mm		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition		Monogram	
Window Glass		Wiper	

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags			
Controls		Cruise Control	
Infotainment Display		OBD Connector	
Music System		Camera	
Rear Left Speakers: No Voice Clarity/ Faulty			
Lights			
Headlight		Interior Lights	
Left: Light Scuff Marks < 50mm			
Tail Light Cluster		Daylight Running Lights	
License Plate Light		Fog Lights	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch		Rear Left AC Vent	
Parking Sensors		Rear Defogger	
USB Charging Port		Power/ Manual Windows	

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Goggle Holder: Lock/ Unlock Not Working			
Cup Holder		Glove Box	
		Sunvisor	
Steering Wheel		Left: Sunvisor LHS Vanity Mirror Light Not Working	
Seat Upholstery		Manual Seat Movement	
Driver Seat: Minor Smudge/ Cracks			
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	

Carpet		Headliner	
Rear View Mirror		Toolkit	

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Life remaining

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE