



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



# 2022 NISSAN SUNNY S | 96,739 KM

VIN: MDHBN7AD8NG142843

# **Car highlights**



## **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



#### **Bluetooth**

Enjoy your drive with bluetooth

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



## **Music System**


Enjoy your drive with music system



## **Amazing Comfort**


Power driver seat

#### **Basic Details**



# **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



ABS	<b>~</b>	Central Locking	<b>✓</b>
Child Safety Locking	~		
्रव Entertainment			
Bluetooth Player	<b>✓</b>	Infotainment System	~
USB player	~		
Exteriors			
Halogen Headlights	~		


## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A Pillar	<b>✓</b>	Right A Pillar	~
Left A to B Pillar Beading	<b>✓</b>	Right A to B Pillar Beading	<b>✓</b>
Right A to B Pillar	<b>✓</b>	Left B Pillar	<b>✓</b>
Left B Pillar Trim	<b>✓</b>	Left B to C Pillar Beading	<b>✓</b>
Right C Pillar Trim	<b>✓</b>	Right B to C Pillar	<b>✓</b>
Right B to C Pillar Beading	<b>✓</b>	Left C Pillar	<b>✓</b>
Running Board Condition			
Left Running Board	<b>✓</b>	Right Running Board	<b>✓</b>
Windshield Condition			
Front Windshield	<b>✓</b>	Rear Windshield	<b>✓</b>
Structural Assessment			
Chassis Condition	<b>✓</b>	Apron	<b>✓</b>
Boot Floor	<b>✓</b>	Firewall Condition	<b>✓</b>
Cowl Top	<b>✓</b>	Head Light Support Condition	<b>✓</b>
Cowl Top			
Cowl Top	<b>✓</b>		
Rear View Mirror Condition			
Left Hand Side Mirror	<b>✓</b>	Left Side Mirror	<b>✓</b>
Right Side Mirror	<b>✓</b>		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	<b>✓</b>		
Wheel cover	<b>✓</b>	Antenna	<b>✓</b>
Grill Condition	(!)	Monogram	<b>~</b>
Light Scuffing < 50mm			
Window Glass	<b>✓</b>	Wiper	<b>✓</b>
Panel Condition			
Rear Trunk Panel	~		

Engine & Transmission			
Engine			
Engine Body	<b>✓</b>	Engine Performance	<b>✓</b>
Engine Oil (Condition & Level)	<b>✓</b>	Exhaust System	<b>✓</b>
Radiator Condition	<b>✓</b>	Radiator Coolant	<b>✓</b>
Fuel System			
Fuel Tank	<b>✓</b>		
Transmission Operation			
Gear Shifting	<b>✓</b>	Drive Axle	<b>~</b>
Transmission Fluid	<b>✓</b>		
Steering, Suspension & Brakes			
Steering			
Steering wheel	<b>✓</b>		
Brake System			
Parking Brake	<b>✓</b>	Brake Master Cylinder	<b>✓</b>
Brake Disc & Brake Pad	<b>✓</b>	Brake Fluid	<b>✓</b>
Suspension			
Shock Absorbers	<b>✓</b>		
Electricals, Controls & Lights			
Keys			
Master Key	<b>✓</b>		
Door Locks			
Child Safety Locking	<b>✓</b>		
Dashboard			
Instrument Panel	<b>✓</b>		
Airbags			
Airbags	<b>✓</b>		





Tyres Condition			
Left Hand Side Front Tyre	~	Left Hand Side Rear Tyre	<b>✓</b>
Right Hand Side Front Tyre	~	Right Hand Side Rear Tyre	<b>✓</b>
Spare Tyre	~		
Life remaining			
LHS Front Tyre	<90%	LHS Rear Tyre	<65%
RHS Front Tyre	<90%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE